

E 1/4 Corner of Section 10

660

MON Wood Post

WIT

#1 Tamarack 10" N46E 15 Lks

#2 Tamarack 10" S44W 43 Lks

1979 Survey by Ross

MON 1/2" x 24" rebar

WIT

#3 NE Cor. of 10 N35E-20"E. 2662.24 ft.

#4 SE Cor. of 10 S0°-50'-20"W 2668.90 ft.

3 1/2
1/8

Feb 25, 1980 Patrick Leeman, Land
Surveyor Trainee found the 1/2" x 24" rebar
from the 1979 Ross survey

Condition of witnesses


#1 Good

#2 Good

#3 Good

#4 Good

Feb. 25 1980 1 Patrick Keenan
replaced in the exact position the $\frac{1}{8}$ " x
3/4" rebar with a $1\frac{1}{2}$ " x 60" Iron Pipe
filled w/ concrete w/ brass cap marked



10" Dock Spike in the East side of
White Pine 7" N31W 61.24 ft.

10" Dock Spike in the North West side of
Red Maple 7" S30W 83.15 ft.

10" Dock Spike in the South East side of
Red Maple 6" S68W 59.86 ft.

Double Headed Nail in the North side of
Pine Post 4" West 1.79 ft.

Section Corner common to sections

10-11-14.15

GLO

MON Tarnack 10"

WIT

1979 Survey by Ross

MON Ed. 3/4" Iron Pipe

WIT

#1 3 1/4 Cor at 10 N 89° 10' 37" W 2603.61 ft

#2 3 1/4 Cor at 10 N 6° 50' 20" W 2668.90

3h/1g


Feb 25, 1980 1 Patrick Leonard, land
Surveyor Trained found the 3/4" Iron Pipe
from the 1979 survey by Ross.

Condition of witnesses

#1 Good

#2 Good

Feb. 25, 1980 1 Patrick Leeman
replaced in the exact location the
3/4"x20" Iron Pipe with a 1 1/2"x60" Iron
Pipe filled with concrete w/ brass cap
marked



10" Dock Spike in the SE side of
Cherry 7" N30E 376 ft. OST

Double Headed Nail in the East side of
Pine Post 4" South 189 ft.

10" Dock Spike in the Northeast side of
Twin Cherry 7" S57E 1724 ft. OST

10" Dock Spike in the N side of
Cherry 10" S62W 1932 ft. OST

10" Dock Spike in the South side of
Cherry 5" S80E 3674 ft.
Fence West 4 ft.