

SURVEY & REMONUMENTATION

JAN 26 2009

Instrument 200800007821 OR
Liber Page 7 304

SECTION

H-11; ¼ corner common to Sections 27 & 34, T23N, R12W

CONTINUATION

A. Description of original monument and accessories and/or subsequent restoration:

- 1966 – Robert A. Griffin, RLS #13584, found ¾" x 12" iron pipe in road in line with East edge of cemetery, replaced with a 1 ¼" x 42" iron pipe witnessed by 3) S48W SE corner of base of tombstone of Lloyd Boylan & Wife 198.00 and 4) S83W NE corner of East entrance pillar 161.14'.
1969 – Wexford County Road Commission, 2" Pipe 15" Deep (there is a 2" pipe similar S02E about 7'), 5) Metal F.P. 31.20', 6) SW 8" Pine 53.60', and 7) N20E 2" Pine 50.00'.
1973 – Jerry L. Wilcox, RLS #14102, L2, Pg 556 and L1, Pg 109, found 1 ¼" iron pipe, centerline road East-West in line with cemetery fence to South, replaced with standard Wexford County monument witnessed by 7) N20E 4" R. Pine 50.06', 8) S55E 5" Poplar 41.08', and 6) S45W 8" R. Pine 53.93'.
1975 – Jerry L. Wilcox, RLS #14102, L1, Pg 430, found Wexford County monument witnessed by 6-8) above.
1979 – Jerry L. Wilcox, RLS #14102, FD Wex. Co. Mon., Liber 1 Page 430.
1988 – James A. Ray, RLS #25869, found Co. Monument witnessed by 6-8) above.
1993 – Rex E. Pope, PS #39093, Mitchell & Associates survey in Section 34, Fd Wexford Co. Mon witnessed by 6-8) above.
1994 – Donald A. Grier, Jr., LLS #33978, Mitchell & Associates survey in Section 34, monument type and accessories not stated, measurements consistent with position of Wexford County monument.
2001 – Craig J. Pullen, PS #39095, L81, Pg 465, Fd Wex. Co. Mon. w/broken top in C/L 24 Road witnessed by 9) N01E Conc. Mon. 33.00', 7) N24E 10" R. Pine 49.84', 10) S69E 15" Aspen 42.01', and 6) S51W 14" R. Pine 53.90'.
2004 – Gordon L. Bonney, PS #12016, L550, Pg 687, does not state monument type or accessories for this corner.

