

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

Found USGLO Iron Post with Brass cap 0.80' above grade in good condition, left in place; found Cedar Post lying alongside; found 6" (now 14") B. Oak with spike in East side N11°E 48.15'; found spike in Southeast side 4" (now 8") J Pine S78°W 4.75'; found Mag nail in North side 12" B Oak. Accepted USGLO Iron post and cap as a careful and faithful reestablishment of the government corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

Mon – USGLO Iron post with Brass cap left in place.

Wit:	N11°E 48.15	Found spike in East side 14" Black Oak
	S78°W 4.75	Found spike in Southeast side 8" Jack Pine
	S76°E 74.52	Found Mag nail in North side 12" Black Oak
	S11°E 43.11	Set nail and tag in West side 6" Red Pine
	East 36'±	Centerline of N-S "Durfee Road"