

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

Found USGLO pipe with brass cap 1'± West of centerline of N-S Deeter Road and 0.5'± below grade in good condition, left in place, found Mag nail in SW side of 7" USGLO BT (now 18") Red Pine N28°W 36.51; found Mag nail in SW side 15" Oak S31°E 59.17; found Cedar Post with USFS location tag West 18'±. Accepted USGLO pipe and cap as a careful and faithful Reestablishment of the government corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

Mon – USGLO pipe with brass cap in good condition left in place.
Wit: N28°W 36.51 Found Mag nail in Southwest side 18" Red Pine
S31°E 59.17 Found Mag nail in Southwest side 15" Oak
S38°W 54.66 Set nail and tag in Southeast side 14" Red Pine
N19°E 105.02 Set nail and tag in Southeast side 14" Oak
West 18'± Cedar post with bearing location tag