

QUALITY  
SERVICES

MAY 16 1997

NOV 19 1996

LIBER003 PAGE 0414

CONTINUATION OF "A" - DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

- 1964 - Robert Griffin, Ls 13584  
L.C.R.C. - Liber 01, Page 95  
Found Bed Rail and replaced with  
5" x 60" Concrete Monument  
#5 - Fence Post N2°E 33.15'  
#4 - 2" P. Pole Anchor N23°E 70.0'  
#3 - P. Pole N45°E 36.54'
- 1972 - Sammy Barnett, PS 16923  
L.C.R.C. - Liber 02, Page 144  
Found Concrete Monument  
#5 - Corner Fence Post N6°E 33.22'  
#3 - P. Pole N55°E 36.60'