

SURVEY &
REMONUMENTATION

AUG 16 2005

SECTION

REC'D AUG 9 2005

2004 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

1. Public Land Survey

T14N R11W
T N R W
T N R W
T N R W
S
T N R W
S
T N R W
S
T N R W
S

2. Property Controlling
in Section
3. Miscellaneous
Property in Sec.

I-12

VOL 4 339



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED & RECORDED
08/09/2005 11:36:59 AM

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, Norman L. Ochis, in a field survey on January 05, 2005 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

Quarter corner common to Sections 34 and 35, Goodwell Township, Newaygo County.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO J H Mullett
4th Quarter 1837
Set quarter section post
#1 8" Aspen S74°W 10 links (6.6')
#2 8" Black Oak S69°E 8 links (5.28')

Conrad Zimmerman, PE #7301
August 30, 1951
NCRC Sheet ± 1950 and NCRC field notes
Found RR Iron
#3 12" Black Oak N40°W 48.3'
#4 24" Black Oak S30°W 67.1'

OVER

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 5/8" x 18" rod, and a RR iron leaning in hole. The corner is 3' East of centerline of North-South bituminous road. The corner is in centerline of gravel road to the West. The condition of the witnesses are as follows: #1 and #2 are gone, #3 found stump N40°W 48' center, #4 and #5 are in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I removed the 5/8" x 18" rod and set a 4" diameter Harrison cast iron monument 20' long marked "County Surveyor #22439" grouted at surface, as a substantial marker for the quarter corner and is accepted as a careful and faithful reestablishment of the position of the original quarter corner.

#4 32" Black Oak S21°W 67.68'
#5 Telephone Pole S60°E 33.55'
Power Pole N53°E 44.91'
10" White Pine N64°W 82.08'

Reset 40d spike with tag in NW side
Found spike in South side
Set 40d spike with tag in North side
Set 40d spike with tag in NE side

Signed by Norman L. Ochis
Norman L. Ochis

Date July 20, 2005

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on April 28, 2005
Norman L. Ochis, County Representative.
M.L.O.

