
T 32N R05E section 32
Couldn't find the remon corner. Fd long pipe in a marsh in about the right location. Area is flooded.
No evidence found at center section
Truax Rd
Fd. monument locations
Corner location to establish
Fd. iron or steel rod, but not rebar as usual for a surveyed location at fence intersection
Long Rapids Rd
32
33
54097
2018
54109
2020
54096
2024