5

1006 Database-Complete Listing

LEAK DESCRIPTION

Date of Leak : 12/04/72 Time: : MST
Line Number: 5
Location:
Milepost: 1427.00
City: County: Mackinac State: MI
Tract: 4-199A
Landowner: State of Michigan

Part of System Involved: Line Pipe
Item Involved : Pipe
Cause: Weld cracked open 3 in.
Number of People Injured: 0
Number of People Killed : 0
Was there an Explosion ? No
Was there a Fire ? No
Leak enter Watercourse ? No
Estimated Damage: 0
Barrels Out: 100
Barrels Recovered: 0
Depth of soil cover: 0 ft.

Government Agencies: Mr. Ronald Shaver - Michigan DNR
Michigan Public Service Commission
Federal EPA

Was it DOT Reportable? NO
Was Drug Testing Performed? No
Temporary Repair: Date: / /
Permanent Repair: 18"x30" Plidco sleeve installed, welded. Date: / /
Line Shutdown: : / / Pressure at Shutdown:
Returned to Service: : / /
Pipe Analysis Performed? No

Pipe Information

Size: 30 In.
Wall Thickness: 0.0000
Date Installed: / /
Yield Strength: 0
Manufacturer:
Seam Type:
Spec. Manufacturer:
Coating:
Maximum Operating Press.: 0 psi

Hydrotest Data

Date: / / Test Press.: 0 psi Test Medium: Test Duration: 0 hrs

Internal Inspection:

Date: / / Type of Tool: Anomolies:

Disposition of Lost Commodity: Soaked into ground
Land Restoration Method: Burned; excavated
Comments: Weld on an inserted patch failed and cracked open 3".

FB 6311845

CONFIDENTIAL