Time: 17-MAR-1994 12:02:16.56
From: SPMS16::BAY_CITY
To: @EA,@DU,@BC
CC:
Subj: PRELIMINARY INCIDENT REPORT

EA Brian MacNeill
EA Neil Goeson

DU Hugh Sangster
DU Roger Argument
DU George Maas
DU Paul Norgren
DU Denise Hamshen
DU Kim Goheen

Shawn

PRELIMINARY INCIDENT REPORT

A. Date of Incident: 3-16-94 0600 MST.

Time of Incident(MST): 0800 MST (OBSERVED BY PILOT/JOHN HAMPSON)

B. Location & Line No.: MP 1730.9, 1/8 MILE UPSTREAM OF SMITHS CREEK ROAD, ST CLAIR COUNTY, MARYSVILLE, MI.

C. Type of Material Released: CRUDE OIL - LSB.
Barrels Out: APPROXIMATELY 20 - 25 GALLONS.
Barrels Recovered: 10 GALLONS.

D. Description of Incident: SMALL PUDDLE OF OIL ON THE GROUND.

14-15 inches

E. Apparent Cause of Incident: 3" CRACK WITHIN A 2-1/8" DEEP DENT LOCATED AT 12:00 ON THE 30" PIPE.

during installation coating

F. How was incident discovered?: PATROL PILOT - JOHN HAMPSON DURING ROUTINE AERIAL PATROL.

1. First LPL employee notified of incident: JOHN HAMPSON - PATROL PILOT CONTACTED LINE 5 OPERATOR - CHERYL.

2. Date and time notification was received (MST): 3-16-94 0800 MST SUPERIOR CONTACTED. 0813 MST BAY CITY CONTACTED. 0814 MST D_L FRITZ_CONTACTED AND 0834 BILL SHARRATT_CONTACTED.

3. LPL employee who confirmed leak: JOHN HAMPSON.

4. Date and time leak was confirmed (MST): 3-16-94 0800 MST. JOHN HAMPSON LANDED AT ST CLAIR COUNTY AIRPORT AND DROVE A VEHICLE TO VERIFY THAT CRUDE OIL WAS ON THE GROUND.

5. Date and time line was shutdown or isolated (MST): 3-16-94 0802 MST LINE 5 SHUTDOWN.

G. Safety & environmental concerns in the area: N/A.

1. Brief description of affected area: WOODED AREA, SPARSELY POPULATED.

2. Proximity to the public: NEAREST HOME - 300 FT.

3. Proximity to bodies of water: N/A.

4. Were there any fatalities or injuries?: NONE.
(if so, provide details of each at the end of report including extent of injury, names/occupations and hospitalization)

ENBDNR0004731

THE NORTHWEST.

H. Briefly describe containment and recovery efforts: USED VACUUM TRUCK AND VACUUMED UP THE OIL. CONTAMINATED DIRT WAS STORED IN PLASTIC CONTAINMENT CELL.

I. Describe initial remedial activities (stockpiling, burning, etc.): STOCKPILED.

J. Description of leak repair in detail: INSTALLED 30" X 30" PLIDCO REPAIR SLEEVE AND APPLIED FILLET WELDS TO ENDS.

Availability of damaged parts of the pipeline for analysis: NONE.

K. Government agencies notified: MDNR 1-800-292-4706 (OPERATOR 12)
State: MICHIGAN
National Response Center: PETTY OFFICER EASON, 1-800-424-8802 REPORT 230430.
Other: ST CLAIR/MARYSVILLE POLICE DEPARTMENT 1-313-329-2233.

L. Describe media coverage (if any): NONE.

Name of person completing report: SHANE HENRIKSEN, DOUG FRITZ AMF.

AMF W J SHARRATT