PIPELINE INTEGRITY
DETAILED FEATURE REVIEW
LINE 5 ENO-EMA 2013 MFL WITH 2008 MFL

Line Segment: 5
Date of Most Recent Inspection: 2013
Inspection Technology & Vendor: GE MFL
ILI Report Issue: 1

Date of Previous Inspection: 2013
Inspection Technology & Vendor: GE MFL
ILI Report Issue: 0

Detailed Feature Review Report Completed By: Kaitlyn Korol
Date: February 8, 2016

Detailed ILI Match Review Report Approved By:Gordon Fredine
Date: 1/10/2017

Table of Contents

1. EXECUTIVE SUMMARY....3
2. ILI MATCH REVIEW QA/QC CHECKS....3
3. DETAILED REVIEWS....3
4. CONCLUSION....3

ENBDNR0006290

1. EXECUTIVE SUMMARY

No features meet any review criteria. No action required from detailed feature review.

2. ILI MATCH REVIEW QA/QC CHECKS

The following QA/QC checks were completed on the Line 5 ENO-EMA 2013 GE MFL run:

Case	A Criteria (2013)	B Criteria (2008)	Description	# of features	Comments
1	All	All	Reach (70% depth next ILI run date (Lvl 2 CGR)	0	No action required.
2	All	All	Reach 0.9 RPR by next ILI run date (Lvl 2 CGR)	0	No action required.
3	All	>40%	Healing: 0.3mm/yr or 0.1 RPR/yr	0	No action required.
4	>=40%		No Match	0	No action required.
5	RPR 1.0-1.05		No Match	0	No action required.
6		>=40%	No Match	0	No action required.
7		RPR 1.0-1.05	No Match	0	No action required.

3. DETAILED REVIEWS

None.

4. CONCLUSION

No features meet any review criteria. No action required from detailed feature review.

ENBDNR0006291