# PIPELINE INTEGRITY
## DETAILED FEATURE REVIEW
## LINE 5 WNO-WMA 2013 MFL WITH 2008 MFL

---

Line Segment: 5
Date of Most Recent Inspection: 2013
Inspection Technology & Vendor: GE MFL
ILI Report Issue: 1

Date of Previous Inspection: 2013
Inspection Technology & Vendor: GE MFL
ILI Report Issue: 0

Detailed Feature Review Report Completed By: Kaitlyn Korol
Date: February 8, 2016

Detailed ILI Match Review Report Approved By:Gordon Fredine
Date: 1/10/2017

---

## Table of Contents

1. EXECUTIVE SUMMARY....3
2. ILI MATCH REVIEW QA/QC CHECKS....3
3. DETAILED REVIEWS....3
4. CONCLUSION....3



ENBDNR0006310

## 1. EXECUTIVE SUMMARY

No features meet any review criteria. No action required from detailed feature review.

## 2. ILI MATCH REVIEW QA/QC CHECKS

The following QA/QC checks were completed on the Line 5 WNO-WMA 2013 GE MFL run:

| Case | A Criteria (2013) | B Criteria (2008) | Description | # of features | Comments |
|---|---|---|---|---|---|
| 1 | All | All | Reach (70% depth next ILI run date (Lvl 2 CGR) | 0 | No action required. |
| 2 | All | All | Reach 0.9 RPR by next ILI run date (Lvl 2 CGR) | 0 | No action required. |
| 3 | All | >40% | Healing: 0.3mm/yr or 0.1 RPR/yr | 0 | No action required. |
| 4 | >=40% | | No Match | 0 | No action required. |
| 5 | RPR 1.0-1.05 | | No Match | 0 | No action required. |
| 6 | | >=40% | No Match | 0 | No action required. |
| 7 | | RPR 1.0-1.05 | No Match | 0 | No action required. |

## 3. DETAILED REVIEWS

None.

## 4. CONCLUSION

No features meet any review criteria. No action required from detailed feature review.



ENBDNR0006311