PIPELINE INTEGRITY
SEVERE CORROSION REVIEW
LINE 5 EAST STRAITS 2008 MFL

Line Segment:
Date of Most Recent Inspection: May 9, 2008
Inspection Technology & Vendor: GE MFL
ILI Report Issue: Issue 1

Date of Previous Inspection: March 24, 2003
Inspection Technology & Vendor: GE MFL
ILI Report Issue:

Severe corrosion Review Completed By: Saheed Akonko
Date:

Severe Corrosion Review Report Approved By:
Date:

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 3

ENBDNR0007492

1.0 EXECUTIVE SUMMARY

The East Straits of Line 5 was inspected on May 9, 2008 using MFL technology. A total of 139 metal loss features were reported, all of which were identified as manufacturing defects. This is similar to the 2003 run that also identified 139 manufacturing metal loss features

In accordance to PI-19 Severe Corrosion Feature Review guideline document, there were no features that meet the severe corrosion criteria.

ENBDNR0007493