

Robert Griffin #13584 in section 7 (22-12), a 1982 survey by Wilcox in section 6 (22-12), a 1982 survey by Griffin again in section 7 (22-12), a 1985 survey by Ed McCombs #10696 in section 1, a 1990 survey by Cole in section 1, and a 1992 survey by Robert Wetherell #24624 in section 13. Properties have been described, bought and sold relying on Coles original proportions. Griffin found a 6 foot error in Coles measurement between the SE 13 and the E1/4 13 prior to 1982. At that time he choose not to disrupt the surveys performed by Cole. He then proportioned and monumented the remainder of the proportioned corners not monumentd by Cole and this is why the proportions I found at first looked suspicious. I am accepting the proportioned corner locations by Griffin and I am unwilling to move these monuments and disrupt the property owners previously surveyed boundaries with a more technically correct mathematical position. This monument is accepted as the best available evidence of the position of the original corner.