

2014 STATE OF MICHIGAN, PRESQUE ISLE COUNTY REMONUMENTATION

Received
PRESQUE ISLE COUNTY
01-09-2015 09:11 am.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended
For corners in

<u>Presque Isle</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>33N</u> R <u>5E</u>	<u>I-8</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____

Instrument 201500000113 OR Liber Page 558 979

201500000113
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REG OF DEEDS
01-09-2015 At 09:21 am.
LC-REMON 17.00
OR Liber 558 Page 979 - 980

Register of Deeds Stamp & Figure Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Travis L. Horrocks, in a field survey on June 30, 20 14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-8
SEE BACK



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-8
FOUND CONC MON 40' SOUTH OF CLEARING
S 80° W 25.64' 12" BALSAM W/BLAZE TAG OVERGROWN
S 80° E 9.44' 10" BALSAM BLOWN OVER
S 09° E 4.78' 36" STUMP #15410
N 10° W 3.87' 6" BALSAM #41922
N 75° E (REC EAST) 23.80' 6" BALSAM #41922
N 78° W 9.48' 8" BALSAM #41922

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-8
CONC MON & REMON CAP #59298
40' SOUTH OF CLEARING
S 80° W 25.64' 12" BALSAM (OW) #59298
N 78° W 9.48' 8" BALSAM #59298 OVER #41922 (OW)
S 09° E 4.78' (REC 4.80') 36" STUMP #15410 (OW)
N 10° W 3.87' 6" BALSAM #41922 (OW)
N 75° E (REC EAST) 23.80' 6" BALSAM #41922 (OW)

Revised by Peer Group
in accordance with P.A. 348
Chairman [Signature]
Date 11-04-2014

Signed by [Signature]
Surveyor's Michigan License No. 59298

WITNESS TAGS & NAILS USED

Date 11/04/14

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975
Revised Jan. 1983
Revised Oct. 1995