

SURVEY &
REMONUMENTATION

FEB 19 2010



DELIVERED TO NEWAYGO CO.
02/09/2010 3:36:20 PM

2009 Newaygo County Remonumentation Project

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Newaygo
(County)

Located in:

Corner Code #

1. Public Land Survey

T14N	R11W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W

2. Property Controlling

in Section S

3. Miscellaneous

Property in Sec. S

VOL. 6

228



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
02/09/2010 3:40:35 PM

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat

5. Private Claims

I, Norman L. Ochs, in a field survey on November 2, 2009 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below.

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

Section corner common to Sections 22, 23, 26 and 27, T14N R11W, Goodwell Township.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - J.H. Mullett
4th Quarter 1837

Set post corner

#1 40" Pine S67°W 22 links (14.52")

#2 Beech N30°W 42 links (27 72')

Robert A. Griffin, R.L.S. # 13584 NOT FOR THIS CORNER
LCRC # 451
October 31, 1977

Found old fence corner

Post marking corner

Set 5" x 60" Concrete Monument

#3 6" White Oak N4°E 12.93'

#4 3" Maple N87°E 32.87'

#5 9" Maple N49°W 59.50'

#6 4" x 7' Post South 1.2'

OVER%

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 1/2" bent Rebar directly over a 5" square x 60" long Concrete USFS Monument with brass cap. The corner is 4' North of centerline of an East and West Gravel Road. The corner is 12'± East of the centerline of a Dirt Road running South and in line with fence remains to the North. The condition of the witnesses are as follows: #1 and #2 gone, #3 thru #6 not for this corner, #7 thru #9 in good condition, #10 gone, #11 in good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I accepted the 5" square x 60" long Concrete USFS Monument with brass cap as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Section Corner.

#7 11" White Oak N06°E 46.02'

#8 13" Red oak S38°E 40.32'

#9 10" Red Oak N54°W 67.98'

#11 4" x 7' Pine Post N05°E 31.87'

21" Red Oak N70°W 51.43'

Found dock spike in West face

Set 60d spike with tag in Northeast face

Found dock spike in Northwest face

Nail in West face

Set 60d spike with tag in South face

Signed by

Norman L. Ochs

Norman L. Ochs

Date January 29, 2010

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Approved by Peer Review Group on October 28, 2009

Norman L. Ochs, County Representative.

M.L.O.

