

SURVEY &
REMONUMENTATION

FEB 19 2010



DELIVERED TO NEWAYGO CO.
02/09/2010 3:36:20 PM

SECTION 2009 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

VOL. 6 230

1 Public Land Survey

T14N	R11W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
02/09/2010 3:40:35 PM

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

I, Norman L. Ochs, in a field survey on November 2, 2009 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be
Recorded on this certificate.

One Quarter Corner common to Sections 23 and 26, T14N R11W, Goodwell Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - J.H. Mullett
4th Quarter 1837

A 30" Pine for Quarter Section Post

Robert A. Griffin, R.L.S. # 13584
LCRC # 450 October 31, 1977
Established equal distance and on a straight line between
controlling corners.
5" x 60" Concrete Monument with brass cap
#1 3" Red Oak N57°E 45.01'
#2 3" Red Pine N41°W 61.20'
#3 4" x 7' Post South 1.1'
#4 6" Maple S3°W 70.10'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER.

I found a 5" square x 60" long Concrete USFS Monument with brass cap projecting 1 foot above grade. The corner is 22'± North of the centerline of an East and West Gravel Road The condition of the witnesses are as follows: #1 and #2 gone, #3 found 4" x 7' Post South 1 1', #4 in good condition

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I accepted the 5" square x 60" long Concrete USFS Monument with brass cap as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter Corner.

#4 10" Maple S07°W 70.10'
11" Maple N62°W 12.39'
11" Red Oak N15°E 20.92'
12" Maple N73°E 30.81'

Found dock spike in West face
Set 60d spike with tag in South face
Set 60d spike with tag in East face
Set 60d spike with tag in North face

Signed by Norman L. Ochs Date January 29, 2010

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on October 28, 2009
Norman L. Ochs, County Representative

M. L. O.

