



DELIVERED TO NEWAYGO CO.
02/09/2007 11:46:35 AM

SURVEY &
REMONUMENTATION

2006 Newaygo County Remonumentation Project

FEB 28 2007

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in
Newaygo
(County)

Located in: Corner Code #

1. Public Land Survey

T14 N	R11 W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W

K-9

VOL. 5 233

2. Property Controlling
in Section
3. Miscellaneous
Property in Sec.

S
S
S
S



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
02/09/2007 11:47:49 AM

Register of Deeds Stamp & File Number

4. Lot No. Recorded Plat
5. Private Claims

I, Norman L. Ochs, in a field survey on January 30, 2006 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be
Recorded on this certificate.

Section corner common to Sections 23, 24, 25, and 26, Goodwell Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR
SUBSEQUENT RESTORATION:

GLO - J.H. Mullett
1st Quarter 1839
Set post corner
#1 10" Aspen S89°E 14 links (9.24')
#2 10" Aspen S20°W 26 links (17.16')

Robert L. Wetherell R.L.S. #24624
May 14, 1996 File No. 7581-96
#6 12" Red Pine N47°W 56.92'
#4 Post South 33.02'
#3 6" White Oak S49°E 50.10'
#7 18" Red Pine N08°W 52.75'

Robert A. Griffin R.L.S. #13584
April 7, 1978 LCRC #450
Set 5" square x 36" Concrete Mon. with brass cap from old fences
#3 4" White Oak S49°E 50.10'
#4 4" square x 7" Post South 33.02'
#5 1/2" Pinch Pipe Southwest 46.56'
#6 7" Red Pine N47°W 56.92'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR
REESTABLISHING CORNER:

Found Robert A. Griffin's concrete monument with brass cap 0.5'± below grade that he set by recovering the location of corner relative to the old fence corner Post 33' South of and 33' West of the Section corner. The centerline of the East and West dirt road is 4' North and the corner is on line with East line of Red Pine occupation in the Northwest quadrant. The condition of the witnesses are as follows: #1 and #2 gone, #3 good condition, #4 4" x 4" Pine Post South 33.02' found nail and tag in East side., #5 found 1/2" Pinch Pipe S45°W 46.56', #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE
LOCATING THE POSITION OF THE CORNER:

Accepted Robert A. Griffin's square concrete monument with brass cap 0.5' below grade as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original section corner.

#3 6" White Oak S49°E 50.10'
#6 10" Red Pine N47°W 56.92'
#7 18" Red Pine N08°W 52.75'
18"-18" Twin White Oak N17°E 37.20'

Found cabin spike in Southwest side.
Found cabin spike in Northeast side.
Found spike in West side.
Set 40d spike with tag #22439 in East side.

Signed by Norman L. Ochs Date February 5, 2007
Norman L. Ochs

Surveyor's Michigan License No. 22439 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on June 29, 2006
Norman L. Ochs, County Representative.

M.L.O.