

SURVEY &
REMONUMENTATION

FEB 04 2008

IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE

SECTION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO

(County)

Located In:

Corner Code #

1. Public Land Survey

T24N R5E

C-3

2. Property Controlling

S

in Section

3. Miscellaneous

S

Property in Sec.

S



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS



LCRC 2007 75

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William J. Rigg, P.S., in a field survey on November 9, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO: Set Post

B. Ash 8", S43E 8lks,

Cedar 10", N43W 11 lks

LCRC'S

1989, LCRC 89-04, Shellenbarger 30101, Set 1/2" bar and cap

Surveys:

1989, Shellenbarger 30101, Set 1/2" bar and cap (liber 376, page 692)

2003, Quaine 33984, found and accepted 1/2" bar and cap (liber 775, page 819)

2006, William Woods P.S. visited corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Rod in position as shown on LCRC's and surveys. Accepted 1/2" rod as best available position for corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced rod with 5/8" rerod and remon cap.

Found N30°W 5.45' 10" Cedar Set New Spike 5.34'

Found East 11.12' 15" Cedar Set New Spike 11.14'


Found South 8.91' 15" Cedar Set New Spike 9.05'

Found South 396'+/- Centerline Creek

Set S40°W 25.20' 12" Cedar

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-06-07

William E. Woods



Signed by *[Signature]*

Surveyor's Michigan License No. #41108

Date November 9, 2007