

SURVEY &
REMONUMENTATION

FEB 04 2008

SECTION
IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO

(County)

Located In:

Corner Code #

1. Public Land Survey

T24N R5E

C-4

2. Property Controlling in Section	S	T	R
3. Miscellaneous	S	T	R
Property in Sec.	S	T	R



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS



LCRC 2007 . 88

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William J. Rigg, P.S., in a field survey on November 9, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:
GLO: Set Post in Marsh
Tamarack 8" S54E 1.22 lks

LCRC'S

Surveys:

2003, Quaine 33984, found and accepted 1/2" bar and cap (liber 775, page 819)
2006, William Woods P.S. corner history sheet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Capped iron #37278 in position as shown on surveys. Accepted iron as best available position for corner.


ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-06-07

William E. Wood

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced iron with 5/8" rerod and remon cap.

Found S25°W 17.68' 12" Birch
Found S45°E 17.22' 8" White Pine
Found S30°E 33.27' 36" White Pine
Found N45E 22.11 18" W. Pine



Signed by

William E. Wood

Surveyor's Michigan License No. #41108

Date November 9, 2007