

**SURVEY &
REMONUMENTATION**

FEB 04 2008

**IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO
(County)

Located In: Corner Code #

1. Public Land Survey

T24N R5E C-3
T R
T R
T R
T R
S
S
S
S

2. Property Controlling
in Section

3. Miscellaneous

Property in Sec.



12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITA M. COYLE, REGISTER OF DEEDS



LCRC 2007 . 87

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, **William J. Rigg, P.S.**, in a field survey on **November 9, 2007** do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO: Set Post

W. Pine 20" S30W 25 lks

W. Birch 6" N25W 60 lks

LCRC'S

1977, LCRC 77-17, Miller 16050, Found Pipe

2005, LCRC 2-2005, Lapham 27595, found 4" Concrete Mon.

Surveys:

1977 Miller 16050, found and witnessed pipe

1986 Lapham 27595 found 1 1/2" pipe

1987 Lapham 27595 found 1 1/2" pipe

2003, Quaine 33984, found and accepted 1/2" bar and cap
(Iber 775, page 820)

2004 Lapham 27595, found 4" concrete monument

2006, William Woods P.S. corner history sheet

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found concrete monument in position as shown on LCRC's and surveys. Accepted concrete monument as best available position for corner.

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-06-07

William Woods

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:


Left conc. monument as found

Found N86°E 42.00' 12" Oak

Found S31°E 57.30' Tri Birch

Found S03°W 48.45' Power Pole

Found S44°W 28.46' 12" Oak



Signed by *[Signature]*

Surveyor's Michigan License No. #41108

Date November 9, 2007