

SURVEY &
REMONUMENTATION

FEB 04 2008

IOSCO COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

IOSCO
(County)

Located In: Corner Code #

12/28/2007 1:14:50 PM
STATE OF MICHIGAN - IOSCO COUNTY
FILED
BONITAM. COYLE, REGISTER OF DEEDS



1. Public Land Survey

T24N R5E

E-3

2. Property Controlling
in Section

S
S
S
S

3. Miscellaneous

S

Property in Sec.



LORC 2007 85

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, William J. Rigg, P.S., in a field survey on November 9, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

A. Description of original monument and accessories and/or subsequent restoration:

GLO: Set Post
W. Pine 20" N2E 65 lks
Y. Pine 24" S20W 44 lks
LCRC'S
1976 John Oliver, found 1-1/2" pipe
Surveys:
1976 John Oliver found 1-1/2" pipe
1993 James Granger, references corner
2004 Lapham 44285, Found 1/2" pipe
2006 Rigg 41108, found 1/2" pipe
William Woods, corner history sheet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" Pipe in position as shown on LCRC's and surveys. Accepted 1/2" pipe as best available position for corner.


ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 11-06-07

William E. Woods

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced pipe with 5/8" rod and remon cap.

Set N45°E 29.62' 10" White Pine
Found N76°W 29.85' 10" Oak
Found N28°W 20.50' 8" Oak
Found S70°E 40.44' 20" Oak



Signed by 
Surveyor's Michigan License No. #41108

Date November 9, 2007