

E $\frac{1}{2}$  SE $\frac{1}{4}$  Except 525 Acres S $\frac{1}{4}$   
T25NR2E

March 24, 2003 Work done  
T. KESSEL

OBLITERATED 1981 POSTING  
AROUND E $\frac{1}{2}$  SE $\frac{1}{4}$  EXC. 525 AC  
DUE TO 1996 ACQUISITION  
OF THAT PARCEL.



March 24, 2003  
 Terry Kessal Survey tech

Removed monuments

NE corner of the South 25 acres  
 of the Southeast  $\frac{1}{4}$  of S4 T25NR2E  
 a  $\frac{3}{8}$  rerod with plastic cap 13589. Also  
 removed bt tags

NW corner of the South 25 acres  
 of the Southeast  $\frac{1}{4}$  of S4 T25NR2E  
 a  $\frac{3}{8}$  rerod w/plastic cap 13589. A removed

BT tag

CE  $\frac{9}{16}$  S4 T25NR2E a  $\frac{3}{8}$  rerod w/plastic  
 cap 13589. Also removed BT tags. This  
 POSITION WAS ERRONEOUS

Maintained  $\frac{1}{4}$  S41S3

Found #3 now a stump. Painted bottom blaze  
 #4 God NAIL in NE Face at record distance

#4 19" ORK common NAIL N Fac

#5 didn't find

#6 dead and leaning

ADDED

8" Maple N16W 95.62' God NAIL NE Face

10" Maple S8W 23.40' God NAIL SE Face

4" Fence Post S80W 2' had God NAIL S Face

J. L. DARLING CORP. TACOMA, WA 98424-1017  
 www.RiteInTheRain.com

No. 302

CE 1/4 SATZ5NR2E (Removed)  
3/24/03

E 1/4 SATZ5NR2E

E 1/2 SE 1/4 Except 5.26 Acres  
SATZ5NR2E

Removed Property boundary Sign  
From wood post

NEW CORNER OF S25 Acres (Removed)  
3/24/03

Removed Property boundary Sign  
From wood post

Removed Property Boundary Sign  
From wood post

NE CORNER OF the  
S25 Acres (Removed)  
3/24/03

100' wide trail road

S25 Acres of the Southeast 1/4  
OF SATZ5NR2E

4 STRAND BARBED WIRE FENCE

T 25 N R 2 E

1981 TRAVERSE BY JOHN WILLIAMS  
RECOMPUTED 3/4/03 TWK

\* NOTE - SHOULD CLOSE TRAVERSE!  
PRIOR TO SUBDIVIDING SECTION!  
ALSO NEED TO VERIFY N-S POSITION  
OF S1/4 CORNER!!

