

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 32 NR 2 E
T 32 NR 3 E

----- Montmorency ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 13-24-18-19

DESCRIPTION OF CORNER MONUMENT 1" pipe with a 4" brass cap

WITNESSES TO CORNER 14" R. Pine S 11 E 189 1/2 links

14" R. Pine West 256 1/2 links


7" Aspen N 49 E 8 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a survey in this area. Government BTs removed in fire line construction. Set corner on line over 1/4 and section corner west, which are good government corners, making the east 1/2 mile equal to the west 1/2 mile between 13 and 24. Corner falls in N-S fire line road. This position was considered more in conformity with the calls of the government survey, since a single proportion on the town line between corners 1 mile north and 2 1/2 miles south, which cannot be identified as government corners, would place the corner of 18-19-13-24 about 65 links north of our established position and far beyond the usual inconsistency of the government survey. This position is further supported by line tree sites in the east 1/2 mile between 13 and 24.

Corner was placed and witnessed November 12, 1958.

SURVEYORS SEAL



SIGNED Kenneth J. Ostling
REGISTERED LAND SURVEYOR

DATE 11/19/58

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 32. NR. 3 E.

Montmorency COUNTY

DESCRIPTION OF CORNER 1/4 Corner common to Sections 18 and 19

DESCRIPTION OF CORNER MONUMENT 1" pipe with a 4" brass cap

WITNESSES TO CORNER 8" Balsam S 44 E 36 1/2 links

5" Balsam N 52 W 5 1/4 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by proportionate measurement between section corners by Forestry Division survey crew while making a survey in this area. Could not identify government Cedar BTs, although there are many in vicinity which do not conform to government record.

Corner was placed and witnessed November 13, 1958.



SIGNED *Kenneth J. Ostling*
REGISTERED LAND SURVEYOR

DATE 11/19/58

RECEIVED
MONTMORENCY CTY.
ATLANTA, MI.

JUL 22 10 37 AM '87
VIVIAN R. SEYMOUR
REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Montmorency
(County)

Located In: Corner Code #

- 1. Public Land Survey
 - T 32N R 3E A-7
 - T 32N R 3E A-6
 - T 32N R 3E A-5
 - T 32N R 3E A-4
- 2. Property Controlling in Section
 - S T R
 - S T R
- 3. Miscellaneous Property in Sec.
 - S T R
 - S T R

35

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

I, Delmer Porter, in a field survey on Dec. 16, _____, 19 86, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- A-4 GLO Notes
- A-5 GLO Notes
- A-6 GLO Notes
- A-7 GLO Notes

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- A-4 Found 2" Pipe in Concrete by Sharfe (Cons. Corps.)
- A-5 Found 2" Pipe in Concrete & 4" X4" Staky by Sharfe (Cons. Corps)
- A-6 Found 1/2" Rod & Cap (Don Marlatt)
- A-7 Found Conservation Mon.w/Brass Cap

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- A-4 2" Pipe in Concrete
 - N34°W 22.14' 10" Maple
 - T68°E 7.90' 10" Triple Maple
 - T13°W 14.27' 8" Maple
 - S63°W 24.78' 8": Maple
- A-5 2" Pipe in Conc.
 - N28°W 8.27' 10" Cedar
 - N77°# 9.70' 8" Cedar
 - S11°E 2.50' 8" Cedar
 - S82°W 15.80' 12" Cedar
- A-6 1/2" Rod & LLS Cap #18660
 - N53°W 40.43' 6" Jack Pine
 - North 2.08' 8" Jack Pine
 - S86°E 42.74' 12" Oak
 - S29°W 30.62' 10" Jack Pine
- A-7 Conservation Monument
 - N89°W 17.28' 10" Twin Oak
 - S56°E 39.47' 10" W. Pine
 - S21°E 40.20' 6" W. Pine
 - S36°W 48.01' 10" Oak



Signed by Delmer E. Porter
Surveyor's Michigan License No. 15410

Date January 26, 1987

ORIGINAL

RECEIVED
MONTMORENCY CTY.
ATLANTA, MI.

JUL 22 10 39 AM '87
VIVIAN R. SEYMOUR
REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Montmorency
(County)

Located In:	Corner Code #
T <u>32N</u> R <u>3E</u>	<u>B-5</u>
T _____ R _____	_____
T _____ R _____	_____
T _____ R _____	_____
2. Property Controlling in Section S _____ T _____ R _____	_____
S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec. S _____ T _____ R _____	_____
S _____ T _____ R _____	_____

36

Register of Deeds Stamp & File Number

- 4. Lot No. _____, Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5	●												
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Delmer E. Porter, in a field survey on Dec. 16, 19 86, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-5 G.L.O. Notes

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5 Found old 4"X4" Stake
Set 1/2" Rod & LLS Cap #15410
(This location was found to be acceptable and relative to the S.E. Ce. Cor. & the S.W. Sec. Cor.)



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5 1/2" Rod & LLS Cap #15410
N04°E 15.43' 6" Cedar
N59°E 4.77' 6" Cedar
S50°W 0.90' 4" Cedar
S54°W 9.99' 8" Cedar

Signed by Delmer E. Porter

Date January 20, 1987

Surveyor's Michigan License No. 15410

ORIGINAL

RECEIVED
MONTMORENCY CTY.
ATLANTA, MI.

JUL 22 10 38 AM '87

VIVIAN R. SEYMOUR
REGISTER OF DEEDS

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montmorency (County)	Located In:	Corner Code #
1. Public Land Survey	T 32N R 3E	C-3
	T 32N R 3E	C-4
	T 32N R 3E	C-5
	T 32N R 3E	C-6
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

37

Register of Deeds Stamp & File Number

I, Delmer Porter, in a field survey on December 16, 19 86, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- C-3 GLO Notes
- C-4 GLO Notes
- C-5 GLO Notes
- C-6 GLO Notes

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- C-3 Found 2" Pipe in Concrete by Sharfe(Conservation Corps) Set 1/2" Rod & LLS Cap#15410 inside
- C-4 Found 2" Pipe in Concrete by Sharfe(Conservation Corps)
- C-5 Found 2" Pipe in Concrete by Sharfe (Conservation Corps)
- C-6 Set 1/2" Rod & LLS Cap by Single Proportion

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-3 2" Pipe c 1/2" Rod & LLS Cap #15410 In Conc. Mon.
N35°W 34.90' 12" Jack Pine
N74°E 33.28' 4" Jack Pine
S79°W 69.88' 12" Triple Oak
N40°W 5.88' 6" Jack Pine
- C-4 2" Pipe in Conc.
N15°E 22.19' 10" Cedar
N20°W 21.82' 12" Tamarack
S40°E 14.70' 6" Cedar
S70°W 12.41' 6" Cedar
- C-5 2" Pipe in Conc.
N20°E 38.28' 16" Spruce
N64°E 17.19' 8" Maple
S13°W 48.84' 20" Red Pine
S31°W 33.45' NE Cor. Cabin
- C-6 1/2" Rod & LLS Cap #15410
S85°E 25.08' 10" Balsam
S37°E 18.26' 14" Spruce
S48°W 8.57' 6" Balsam
N80°W 23.40' 10" Balsam

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3			●										
4	7		●		8		9		10		11		12
5			●										
6	15		●		16		15		14		13		
7													
8	19				20		21		22		23		24
9													
10	30				29		28		27		26		25
11													
12	31				32		33		34		35		36
13													



Signed by Delmer E. Porter
Surveyor's Michigan License No. 15410

Date January 26, 1986