

Land Corner Recordation Certificate
Attachment B to 2015 Annual Grant Agreement
Authority: MCL 54.206 and R54.202

This form is **ONLY** for corners filed under the 2015 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2015 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county.

For corner(s) in **Montmorency, Co.** **Albert, Twp.**

Corner Type	Survey Township	Corner Code	
Original Public Land Survey Corner	T <u>T 29 N</u> R <u>02 E</u>	<u>E - 11</u>	1
• MCL 54.202(g)	T _____ R _____	_____	2
• MCL 54.262(g)	T _____ R _____	_____	3
	T _____ R _____	_____	4
			5
Property Controlling Corner	S _____ T _____ R _____	_____	6
• MCL 54.202(i)	S _____ T _____ R _____	_____	7
• MCL 54.262(h)	S _____ T _____ R _____	_____	8
	S _____ T _____ R _____	_____	9
Protracted Public Land Survey Corner	T _____ R _____	_____	10
• MCL 54.202(k)	T _____ R _____	_____	11
• MCL 54.262(i)	T _____ R _____	_____	12
	T _____ R _____	_____	13

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6		5		4		3		2		1		2	
3													3	
4	7		8		9		10		11		12		4	
5													5	
6	18		17		16		15		14		13		6	
7													7	
8	19		20		21		22		23		24		8	
9													9	
10	30		29		28		27		26		25		10	
11													11	
12	31		32		33		34		35		36		12	
13													13	
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

1840 Lewis Clason DS, set. Post. Cor. Sec(s). 28, 29, 32 & 33.

Wit's. (1) Y. Pine 20" S45°E 43 L (28.38')

(2) Do 20" N58°W 8 L (5.28')

Circa

1940 Frank N. Smith P.S. #754, Sec. 32, diagram (Stevens) no corner description. Wit's. (3) Bl. Oak N58°W 38.3' (4) Bl. Oak S38°-30'E 51.7' (5) Bl. Oak S55°-10'W 61.9' (NOTE) MCRC Sec. 32 diagram indicates same wit's.

Circa

1970(s) Kenneth J. Ostling P.S. #10068 (DNR Surveyor) found corner as shown on Twp. diagram. No corner description or wit's.

HISTORY CONTINUED ON BACK OF SHEET