

Land Corner Recordation Certificate
Attachment B to 2015 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2015 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2015 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county.

For corner(s) in **Montmorency, Co. Albert, Twp.**

Corner Type	Survey Township	Corner Code	
Original Public Land Survey Corner	T <u>T29N</u> R <u>02E</u>	<u>E - 12</u>	1
• MCL 54.202(g)	T _____ R _____	_____	2
• MCL 54.262(g)	T _____ R _____	_____	3
	T _____ R _____	_____	4
			5
Property Controlling Corner	S _____ T _____ R _____	_____	6
• MCL 54.202(i)	S _____ T _____ R _____	_____	7
• MCL 54.262(h)	S _____ T _____ R _____	_____	8
	S _____ T _____ R _____	_____	9
Protracted Public Land Survey Corner	T _____ R _____	_____	10
• MCL 54.202(k)	T _____ R _____	_____	11
• MCL 54.262(i)	T _____ R _____	_____	12
	T _____ R _____	_____	13

	A	B	C	D	E	F	G	H	I	J	K	L	M	
1														1
2	6		5			4		3		2		1		2
3														3
4	7		8			9		10		11		12		4
5														5
6	18		17			16		15		14		13		6
7														7
8	19		20			21		22		23		24		8
9														9
10	30		29			28		27		26		25		10
11														11
12	31		32		33		34		35		36			12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

1840 Lewis Clason DS, set 1/4 Sec. Post.

Wit's. (1) Y. Pine 16" S36°E 32 L (21.12') (2) Do 20" N55°W 32 L (21.12')

Circa 1950 Frank N. Smith P.S. #754, found or placed 2" pipe. No wit's. marked.

1974 Larry G. Beauregard P.S. #18654 (Surveyor for Scott Eng. Co. Inc.), found 2" pipe in c/l of Granholm road 1' below road surface. Filed Act 132, Rec. L. 1, P. 543. No wit's. marked.

1983 & 85, L.G.B. P.S. #18654 (Surveyor for Scott) found 2" pipe 1' below road surface, raised with 1/2" bar & RLS cap. Filed Act 132(s) L. 3, P. 204, L. 10004, P. 312. (1983) Filed LCRC Rec. L. 1, P. 341. Wit's. marked: (3) S85°W 35.37' 6 Oak (4) S45°W 47.26' 6" Oak (5) East 33' DNR Red Top Post.

2002 Donald E. Marlatt P.S. # 18660 found 1/2" rod & cap. Filed Act 132 Rec. L. 1006, Pgs. 57 -59. Wit's. marked. (6) West 8" Oak 52.18' (7) S50°E 10" Oak 57.77' (8) East Tel Box 27.13' (9) N60°E 8" Maple 53.12'

deW