

# Land Corner Recordation Certificate

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Carl T. Kiiskila, P.S. #33981

Field Survey Date: August 8, 2017

For corner(s) in: Montmorency County

## Original Public Land Survey Corner

## Corner Code

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

## Property Controlling Corner

## Corner Code

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

## Property Corner

## Corner Code

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

## Protracted Public Land Survey Corner

## Corner Code

S 32 T 29N R 02E D-12  
 S 32 T 29N R 02E 05  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

## Part A: Corner History

### D-12 – Center ¼ Corner Section 32, T29N, R02E

2002 – Donald E. Marlatt P.S.#18660 – Certificate of Survey L.1006 p.57 – Set ½" rod and cap  
 S60°W 17" Oak 30.70'  
 N60°W 13" J. Pine 27.90'  
 N77°E 8" J. Pine 23.60'  
 N65°E 12" J. Pine 8.40'

### 05 – Center-North 1/16 Corner Section 32, T29N, R02E

N/A – There were no prior surveys in this section that would have established this position.

L-1. P-819

**Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner**

**D-12 – Center ¼ Corner Section 32, T29N, R02E**

Set 2" stamped Aluminum D.N.R. cap on 5/8"x34" rebar (2" AC) per standard B.L.M. procedure and accepted as the best available evidence of the position of the corner. The set 2" AC is located in the intersection of a mowed trail to the South and to the East. A twisted and bent ½" rebar was found stuck in the ground leaning against a tree to the West of the corner position.

**05 – Center-North 1/16 Corner Section 32, T29N, R02E**

Set 2" stamped Aluminum D.N.R. cap on 5/8"x34" rebar (2" AC) per standard B.L.M. procedure and accepted as the best available evidence of the position of the corner. The 2" AC is 22'± East of centerline of North-South two-track trail road and 65'± South of centerline of a Northwest-Southeast two-track trail. Found no other evidence to dispute the position of the corner.

**Part C: Field Evidence of Perpetuation or Monumentation of Corner**

**D-12 – Center ¼ Corner Section 32, T29N, R02E**

**2" stamped Aluminum D.N.R. cap on 5/8"x34" rebar**

**Witnesses:**

N08°E 6.62' to set nail & tag in East side 4" Oak  
N70°E 24.01' to set nail & tag in SE side 12" J. Pine  
South 81.94' to set nail & tag in West side 13" Oak  
N77°W 6.73' to set nail & tag in North side 4" Oak

Set Blue post with location tag 1' North

**05 – Center-North 1/16 Corner Section 32, T29N, R02E**

**2" stamped Aluminum D.N.R. cap on 5/8"x34" rebar**

**Witnesses:**

N16°E 20.88' to set nail & tag in SE side 4" Oak  
S30°E 2.58' to set nail & tag in SW side 11" J. Pine  
S05°W 35.61' to set nail & tag in East side 10" J. Pine  
N58°W 43.07' to set nail & tag in NE side 3" J. Pine

Set Blue post with location tag 1' North

*Carl T. Kiiskila*

Carl T. Kiiskila, P.S.

Professional Surveyor's License No.: 33981

Michigan D.N.R. 1732 W. M-32 Gaylord, MI 49735

*10-23-17*

Date

