

MAY 18 1996

## CHEBOYGAN COUNTY REMONUMENTATION CORNER

## COMMISSION

For corners in  
CHEBOYGANLAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_

(County) \_\_\_\_\_

1. Public Land Survey T. 38N R. 3W M-13  
T. 37 R. 2W A-1  
T. \_\_\_\_\_ R. \_\_\_\_\_  
T. \_\_\_\_\_ R. \_\_\_\_\_

2. Property Controlling S. \_\_\_\_\_ T. \_\_\_\_\_  
in Section S. \_\_\_\_\_ T. \_\_\_\_\_

3. Miscellaneous S. \_\_\_\_\_ T. \_\_\_\_\_  
Property in Sec. S. \_\_\_\_\_ T. \_\_\_\_\_

RECEIVED  
FOR RECORD

96 OCT 30 PM 12:23

*James H. Granger*CLERK/REGISTER  
CHEBOYGAN COUNTY, MICHIGAN  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, JAMES H. GRANGER, in a field survey on SEPTEMBER 24, 19 96  
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points  
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as  
required in the current manual of survey instructions of the United States Department of the Interior,  
Bureau of Land Management or by a decree of a Court of Law and /or that the corner points  
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of  
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,  
recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

## A. Description of original monument and accessories and/or subsequent restoration:

1840 Original Survey  
John MullettSet wood post 8" Spruce N55°E 12 lks  
8" Spruce S51°W 6 lks19772 LCRC  
Orlando Doyle # 7319


Set 3/4" pipe

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" pipe and three Doyle witnesses overgrown.

*Monument Found*

LIBER 010 PAGE 180




## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

also corners A-13, T38N, R2W A-1, T37N, R2W M-1 T37N, R3W

Set 5/8" x 30" rebar with Remonumentation Cap

8" Tamarack	N23°W	7.41'	Set nail w/tag
8" Tamarack	N43°E	10.56'	Set nail w/tag
6" Tamarack	S76°E	5.08'	Set nail w/tag
8" Tamarack	S39°W	5.82'	Set nail w/tag



Signed by

*James H. Granger*

Surveyor's Michigan License No. 16041

Date

10-10-96