SUMVEIS REMONUMENTATION

Surveyor's Michigan License No. 16041

CHEBOYGAN COUNTY REMONUMENTATION CORNER

r 5 1997			IER RECORDATION irement of Act 74, M				
For corners in N	Lo	cated In:	Corner Code #			A 200	_
(County)						RECEIVE FOR RECO	BU B
1. Public Land Sur	rvey	T <u>37N R_3W</u> TR T <u>37</u> R 2 W	M-5 (A-5)		96.1	not 30 PM	12: 28
2. Property Contro in Section	olling S S	TR TR			F 10	pareness	TED
3. Miscellaneous Property in Sec		TR TR			CHEB Register of De	CLERK/REGIS DYGAN COUNT eds Stamp & I	File Number
4. Lot No	_ , Recorded Plat				L B C D E	FGHI	JKL
5. Private Claims					-6-5-	4-3-3	-2-1-
				3 -			
				4 -	—- 	_ 910	-1112-
I, JAMES H. GRANG	ER	, in a field survey	on SEPTEMBER 24	19 96		16 15	
do hereby state that	at under requirements	of P.A. 74, Michig	gan P.A. of 1970, the c h regulations and rules	corner points	-1817		
required in the current	t manual of survey ins	tructions of the Unit	ted States Department of Law and /or that the o	the Interior,	1920	2122	_2324_
mentioned in lines 3,	4 and 5 above were	in conformance wit	th the rules of the Michig	gan Board of 9			+++
recovered, found as ex		ourt of Law; establ	lished, re-established, π	nonumented, 10-	30 29	_2927_	-26-25-
NOTE: Not more the on this cert		same town and ran	nge, may be recorded	11 12- 13	31 32	33 34	3536-
A. Description of o			d/or subsequent restor st 16" Sugar N55°W 6" Beech S45°E	/ 11 lks			
1960 MSHD - Dean Delema		1/2" bar & ba	roken glass				
1980 Survey Orlando Doyle	e # 7319	Found 1/2" b	oar & broken glass				
1991 LCRC Norman Qua	ine #33984		oar & broken glass 2" rod & cap # 15410		,	eboygan	County
B. Description of	corner evidence fou	ind and/or method	applied in restoring or	reestablishing cor	rner:	7	7
Found 1/2" rod	w/ cap # 15410 an	d thrée witnesses.	. <i>IN</i>	and a		OCT 30	1990
			LIBER 010	O PAGE 184	1	e-Monunie	ntation
			2.00% OI(O PAUL TOT		THE STATE OF THE S	
					Service of the servic	of arch	
C. Description of also cor	of monument for co mer A-5, T37N	rner and accessori	es established to perp	etuate locating the	position of the	Te corner: JAMES H. GRANDER	100
Set 5/8" × 30"	rebar with Remonur	nentation cap				rdyereg kan Royeveyor	NO.
1/2" Rod Power Pole	S41°E	43.62' Fd ta	na.		Mark.	16961 a	
Anchor Pole	S64°E	84.85' Fd ta	ıg		Bar Con	Salar Carried	S. Carrier
Anchor Pole 10" Birch		44.05' Fd ta 44.80' Set n	ig nail w/tag				i "

Date 10-10-96