

Escanaba River State Forest  
Gwinn, Michigan  
April 24, 1961

TO: Billy Buckler, Land Surveyor  
FROM: Arne A. Metsa, District Forester  
SUBJECT: List of Corners that Need to be Set

The following is another list of corners that need to be set. These corners have been found since our last list of April 8, 1959.

T43N, R24W

South 1/4 corner, Sec. 33

T42N, R25W

North Sec. Corner between 4 and 5

T45N, R23W

- ✓ Northeast corner Sec. 20
- ✓ East 1/4 corner Sec. 20
- South 1/4 corner Sec. 21
- Northwest Corner Sec. 22
- ✓ Northeast corner Sec. 35

T44N, R21W

East 1/4 corner, Sec. 24

T44N, R26W

Southwest corner of Sec. 18

T44N, R24W

Southwest corner Sec. 10

T44N, R25W

- Meander corner between 22 & 23  
(26.52 ch. N. of south cor.)
- ✓ South 1/4 corner Sec. 35.

AAM:gm