

SURVEYORS MICHIGAN REGISTRATION NO. _____



APPROVED AND SIGNED BY _____
 CHIEF OF SURVEY PARTY
 DATE _____
 MICHIGAN REGISTERED LAND SURVEYOR
 DATE _____
 SIGNED BY *Robert E. Schmeling*
 SURVEYORS MICHIGAN REGISTRATION NO. 8317
 DATE November 12, 1982

FOR STATE AND UNITED STATES AGENCIES:

Replaced above iron pins with a 1" diameter 4' long galvanized iron pipe with brass cap thereon stamped with appropriate identification. Made new bearing trees: Power pole 8" S79°E 35.9 feet to b pole and PK nail (Scribed: NBT) White cedar 10" S61°E 141.6 feet to b tree and PK nail (Scribed: 1/2 S7 NBT) White cedar 14" S38°W 145.6 feet to b tree and PK nail (Scribed: 1/2 S12 NBT) Road sign N33 1/2° W 28.2 feet to nearest edge of east leg of sign. Set 2' north of corner monument a 4" squared cedar stake with aluminum locator tag thereon. All bearings magnetic. Iron pins above placed beside corner monument.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A. Description of original monument and accessories and/or subsequent restoration:
 1/2 corner between Section 7, T42N, R25W and Section 12, T42N, R26W in Marquette County. Bearing trees of the original U.S. government survey as placed by Deputy Surveyor John Burt in August of 1844: Tamarack 10 S35W 9 links - no evidence remains and Tamarack 10 N47W 34 links - no evidence remains. In 1948 the Marquette County Road Commission notes reveal that corner was identified by an iron pipe and old scribed post at fence corner and new bearing trees were made: White birch 10 S11 W 22.9 feet = no evidence remains and white birch 11 S44E 44.2 feet - no evidence remains. Their notes reveal that later, other ties were made as above white birch were no longer effective: Telephone pole 9" S38E 102.8 feet - now the decayed base of pole remains and telephone pole 8" S60W 130.5 feet - now the decayed base of pole remains. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Observed by Robert E. Schmeling and Chuck Walkner the above noted evidence. Found in place staked atop each other 2"-2" diameter by 1 1/4" iron pins. Corner located approximately 40.7 feet south of centerline of County Road 426 where County Road 557 turns north.

I, Robert E. Schmeling, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 12, 1982, established, re-established, monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

FOR CORNERS OF:-	LOCATED IN:-	T.	N.	S.	R.	W.	K.	X.
1. PUBLIC LAND SURVEY	42	42	XX	26				
2. PROPERTY CONTROL-								
3. MISCELLANEOUS								
4. LOT NO. _____, RECORDED PLAT _____								
5. PRIVATE CLAIMS _____								

LAND CORNER RECORDATION CERTIFICATE
 FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

REGISTER OF DEEDS STAMP AND FILING NUMBER

Recorded Jan. 25, 1983
 AT 2:35 PM
 LIBERT 4 OF R2 PAGE 213
 Clerk
 Registrar of Deeds

