

# 2014 STATE OF MICHIGAN, PRESQUE ISLE COUNTY REMONUMENTATION

Received  
PRESQUE ISLE COUNTY  
01-09-2015 09:11 am.

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

**Presque Isle County**  
(County)

Located in:

Corner Code #

Instrument 201500000111 OR  
Liber Page 558 975

1. Public Land Survey T 33N R 5E H-9  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

201500000111  
Filed for Record in  
PRESQUE ISLE COUNTY  
CATHY I. IDALSKI, REG OF DEEDS  
01-09-2015 At 09:21 am.  
LC-REMON 17.00  
OR Liber 558 Page 975 - 976

Register of Deeds Stamp & Figure Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_


I, **Travis L. Horrocks**, in a field survey on **June 10**, 20 **14** do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2												
3												
4												
5												
6												
7												
8												
9												
10												
11												
12												
13												

A. Description of original monument and accessories and/or subsequent restoration:

H-9  
SEE BACK



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-9  
FD. CONC MON AT FENCE COR  
FENCE N-S & WEST  
S 80° E 27.40' (REC 26.4') 24" SPRUCE (NAIL OVERGROWN)  
S 13° W (REC SOUTH) 16.77' 4" BALSAM #41922  
S 65° W (REC S 80° W) 20.33' 7" BALSAM #41922  
N 22° W (REC N 10° W) 32.96' 10" BALSAM #41922

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-9  
CONC MON & REMON CAP #59298 AT FE COR  
FENCE N-S & WEST  
S 80° E 26.4' TO FACE OF 24" SPRUCE #59298  
S 13° W (REC SOUTH) 16.77' 4" BALSAM #41922 (OW)  
S 65° W (REC S 80° W) 20.33' 7" BALSAM #41922 (OW)  
N 22° W (REC N 10° W) 32.96' 10" BALSAM #41922 (OW)

Ratified by Peer Group  
in accordance with P.A. 348  
Chairman *[Signature]*  
Date 11-4-2014

Signed by *[Signature]*  
Surveyor's Michigan License No. **59298**

WITNESS TAGS & NAILS USED

Date 11/04/14

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971

Revised May 14, 1975  
Revised Jan., 1983  
Revised Oct., 1985