

✓
Town 25 north, of Range 2 east

Remarked corner of secs 5, 6, 7 & 8
 of Pin 8 n 87 w 4.48
 Set stone post at corner.
 Following U. S. bearing trees fully identified:
 Spr Pin 4 s 87 1/2 w 2.6
 " " 5 n 38 e 3.1

Sept 22, 1884

John Randall Dep. Comm.

1 Remarked & set post corner secs. 2, 3, 10 & 11
 13 Oak 5 north 70 etc
 No other tree count.

Found bearing tree on Sec. 2 (long elms)
 not on U. S. Field notes. Identified as =
 decayed stumps of following recorded U. S.
 to be

Spr Pin 10 s 88 e 2.0

" " 5 n 45 w 2.6

Jan 15, 1883

John Randall Dep. Comm.
 John Lott, Chairman

Sept 30, 1884

South random between Secs 10 & 11 & continued
 Variation 07 west
 200.32 dist. .06 west of 1/4 section post bet. Secs 2 & 3

North corrected between Secs 2 & 3 and
 continued between Secs 15, 14, 10, 11
 40.06 1/2 Set post corner of Secs. 14, 15, 2 & 3
 Pin 4 s 32 e 14 3/4
 " " 5 s 87 w 2.0

80.12 1/2 Set parallel section post bet. Secs. 14 & 15
 Spr Pin 7 s 52 1/4 w 1.95
 " " 7 n 45 e 1.38 1/2

120.19 1/2 Set post corner of Secs 10, 11, 14 & 15
 Pin 7 n 30 e 8.6
 No other count

(copy from county record)