

Land Corner Recordation Certificate
Attachment B to 2015 Annual Grant Agreement
Authority: MCL 54.205 and R54.202

This form is **ONLY** for corners filed under the 2015 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 - 54.210d and 2015 State Survey and Remonumentation Grant Agreement

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county.

For corner(s) in **Montmorency, Co.** **Albert, Twp.**

Corner Type	Survey Township	Corner Code
Original Public Land Survey Corner	T <u>T 29 N</u> R <u>02 E</u>	<u>E - 10</u>
• MCL 54.202(g)	T _____ R _____	_____
• MCL 54.262(g)	T _____ R _____	_____
Property Controlling Corner	S _____ T _____ R _____	_____
• MCL 54.202(i)	S _____ T _____ R _____	_____
• MCL 54.262(h)	S _____ T _____ R _____	_____
Protracted Public Land Survey Corner	T _____ R _____	_____
• MCL 54.202(k)	T _____ R _____	_____
• MCL 54.262(i)	T _____ R _____	_____

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6		5		4		3		2		1			2
3														3
4	7		8		9		10		11		12			4
5														5
6	18		17		16		15		14		13			6
7														7
8	19		20		21		22		23		24			8
9														9
10	30		29		28		27		26		25			10
11														11
12	31		32		33		34		35		36			12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

1840 Lewis Clason DS, set ¼ Sec. Post.

Wit's. (1) W. Pine 24" N17°E 64 L (42.24') (2) Y. Pine 26" S73°W 26 L. (17.16')
Circa

1940 Frank N. Smith P.S. #754, found 1" pipe & stone at corner while doing a Section Divisional survey of Sec. 29. Wit's. marked (3) 10" Soft Maple 36.1' S85°W (4) 6" Soft Maple 47.35' N45°W

1972 & 74 Larry G. Beauregard P.S. #18654 (Surveyor for Scott Eng. Co. Inc.) found 1" pipe 1.0' below road surface & raised with ½" bar & cap. Filed Act 132(s) Rec. L. 1, Pgs. 270 - 275 & L. 1, Pgs. 544 - 546. Wit's. marked (5) West 33.0' Conc. Mon. (6) S30°E 61.35' P. Pole.

Norman C. Caldwell P.S. #12018, found record iron & wit's. (3) S85°W 36.2' 10" Maple (5) West 33' Conc. Mon. Wit. marked (7) N65°W 39.1' 14" Maple Filed Act 132, Rec. L. 1 Pgs. 191 & 192

de w