

**Land Corner Recordation Certificate
Attachment B to 2017 Annual Grant Agreement
Authority: MCL 54.205 and R54.202**

This form is **ONLY** for corners filed under the 2017 State Survey and Remonumentation Grant Agreement

Filing Requirement: MCL 54.268(2)(a), 54.268(2)(d), 54.201 – 54.210d and 2015 State Survey and Remonumentation Grant Agreement

Instrument Liber Page
201700071814 14 315

Notes:

- No more than two Original Public Land Survey Corners can be recorded on this certificate
- If a corner reported hereon is common to two or more survey townships, each Town, Range and Corner Code for the corner may be identified on this certificate
- If a corner reported hereon is common to two or more counties, each county may be identified on this certificate and a copy of this certificate filed with the Register of Deeds in each county.

For corner(s) in **Montmorency, Co. Albert, Twp.**

201700071814
Filed for Record in
MONTMORENCY COUNTY, MI
TERESA WALKER, REGISTER OF DEEDS
09-08-2017 At 10:02:39 am.
REMONUMENTU 30.00
Liber 14 Page 315 - 316

Corner Type

Corner Code

Original Public Land Survey Corner

- MCL 54.202(g)
- MCL 54.262(g)

T	T 29 N	R	02 E	G - 10
T	_____	R	_____	_____
T	_____	R	_____	_____
T	_____	R	_____	_____

Property Controlling Corner

- MCL 54.202(i)
- MCL 54.262(h)

S	_____	T	_____	R	_____
S	_____	T	_____	R	_____
S	_____	T	_____	R	_____
S	_____	T	_____	R	_____

Protracted Public Land Survey Corner

- MCL 54.202(k)
- MCL 54.262(i)

T	_____	R	_____
T	_____	R	_____
T	_____	R	_____
T	_____	R	_____

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6		5		4		3		2		1			2
3														3
4	7		8		9		10		11		12			4
5														5
6	18		17		16		15		14		13			6
7														7
8	19		20		21		22		23		24			8
9														9
10	30		29		28		27		26		25			10
11														11
12	31		32		33		34		35		36			12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner(s) History

1840 Lewis Clason DS, set 1/4 Sec. Post between Sec(s) (27 & 28) 29/2

Wit's. (1) Hem. 20" S35°E 56 L. (36.96') (2) Beech 9" N55°W 28 L. (18.48')

1974 Larry G. Beauregard P.S. #18654 (Surveyor for R.S. Eng. Co. Inc.) did not find or set this corner while doing a section divisional survey of Sec. 28. Calculated a position by S.P. method only for section break down. As noted in Act 132, Rec. L. 1, Pgs. 544 -546.

1998 Frederick J. King P.S. # 25852 did not set this corner, but did use Beauregard calculated position in his survey in Sec. 28. Filed Act 132 Rec. L. 10005 Pgs. 0056 & 0057.

2011 Donald E. Marlatt P.S. #18660 set or found 1/2" bar & placed his P.S. cap on bar while doing survey of the SE1/4 of the NW1/4 of Sec. 27, T29N, R2E. Rec. L. 1006, P. 759.
NOTE: No tie to 1/4 Cor or wit(s) shown on survey.

Received
MONTMORENCY COUNTY, MI
09-08-2017 10:00 am.

CA M8-
VB