

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 4 p9 72

For corners in  
Oscoda (County)

Located In: Corner Code #

STATE OF MICHIGAN  
OSCODA COUNTY  
FILED

2 AUG 95 9:38 A.M.

PATSY J. PETERS  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

|                                       |   |     |   |    |       |
|---------------------------------------|---|-----|---|----|-------|
| 1. Public Land Survey                 | T | 26N | R | 2E | B - 9 |
|                                       | T |     | R |    |       |
|                                       | T |     | R |    |       |
|                                       | T |     | R |    |       |
| 2. Property Controlling<br>in Section | S |     | R |    |       |
|                                       | S |     | R |    |       |
| 3. Miscellaneous                      | S |     | R |    |       |
| Property in Section                   | S |     | R |    |       |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Marvin E. Myers, in a field survey on June 5, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-W. Coon July 1839

Mon-Post

WIT: 10" Y.Pine S45°W 25 lks.  
14" W.Pine N74°E 18 lks.

US GLO-G. Veal Oct. 1935

Mon-Accept road & fence lines

Set conc. Mon. with

Brass Tablet

WIT: 6" B.Oak N06°E 48 lks.

8" B.Oak S45½°E 60 lks.

S.J.E. Lucas, Jr. Aug. 21, 1947

Mon-US GLO Mon.

WIT: None given

L.2, pg.131 N.Caldwell June 3, 1961

Mon-Fd. US GLO pipe & cap

WIT: 5' South of road C

Fence line North

10" Oak N06°E 31.70'

14" Oak S45°E 39.60'

22" Oak N40°E 48.50'

L.1, pg.205 N. Caldwell July 1972

Mon-Unknown

WIT: None given

L.1, pg.487 N. Caldwell Mar. 27, 1974

Mon-Unknown

WIT: None given

L.3, pg.116 N. Caldwell Sept. 1979

Mon-Unknown

WIT: Iron North 33.00'

Gary Wilson Sept. 21, 1992

LCRC L.3, pg.257

Mon-Fd. GLO Mon.

WIT: 4' South of C E-W Road

5" R.Pine N41°E 59.38'

8" R.Pine S48°E 84.25'

10" R.Pine S29°W 125.55'

Triple Maple N08°W 106.39'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found US GLO Brass Cap monument with iron. Accepted as the best available evidence of the re-establishment of the original corner.

APPROVED

County Remonumentation  
Peer Review Group

NCC/31 700 95  
JULY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Non-US GLO concrete monument

WIT: 5" R.Pine N41°E 59.38'

8" R.Pine S48°E 84.25'


10" R.Pine S29°W 125.55'

West edge carsonite post S07°W 17.18'

USFS Survey Coordinates

Lat 44°37'23" .80041

Long 84°14'29" .16240



Signed by Marvin E. Myers

Date July 28, 1995

Surveyor's Michigan License No. 31600

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983