

2014 STATE OF MICHIGAN, PRESQUE ISLE COUNTY REMONUMENTATION

Received
PRESQUE ISLE COUNTY
01-09-2015 09:11 am.

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Instrument Liber Page
201500000107 OR 558 967

Presque Isle
(County)

Located In: Corner Code #

1. Public Land Survey T 33N R SE G-8
T____ R____
T____ R____
T____ R____

2. Property Controlling in Section S____ T____ R____
S____ T____ R____

3. Miscellaneous S____ T____ R____
Property in Sec. S____ T____ R____

201500000107
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REG OF DEEDS
01-09-2015 At 09:21 am.
LC-REMON 17.00
OR Liber 558 Page 967 - 968

Register of Deeds Stamp & Figure Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, **Travis L. Horrocks**, in a field survey on **March 12**, 20 **14** do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	N
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-8
SEE BACK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-8
FOUND CONCRETE MONUMENT
13' EAST OF CURVE OF S. ROGERS RD.
N 35° W 16.10' 24" DEAD ASH W/60D SPIKE
S 76° W 109.50' STUMP W/BLAZE
N 31° E FE POST ROTTED OFF
FITS SINGLE PROPORTIONAL MEASUREMENT
BETWEEN G-7 & G-9 AND ALSO FITS GLO CALL
TO THE STREAM CROSSING

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-8
CONCRETE MONUMENT & REMON CAP #59298
13' EAST OF CURVE IN S. ROGERS RD.
N 35° W 16.10' 24" DEAD ASH W/60D SPIKE (OW)
N 70° E 38.60' POWER POLE #59298
S 80° E 15.25' 4" SPRUCE #59298
S 76° W 88.10' 12" ASPEN #59298
S 40° W 89.97' 10" WHITE BIRCH #59298

Relified by Peer Group
in accordance with P.A. 345
Chairman *[Signature]*
Date 11-4-2014



WITNESS TAGS & NAILS USED

Signed by *[Signature]*
Surveyor's Michigan License No. 59298

Date 11/04/14

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1973
Revised Jan., 1983
Revised Oct., 1995