

**PRESQUE ISLE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in PRESQUE ISLE Located in: METZ Corner Code #
(County) (Township)

1. Public Land Survey T 33N R 5E G-11
T R
T R
T R
2. Property Controlling S T R
In Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Instrument 201500000075 OR Liber Page 558 931

201500000075
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REG OF DEEDS
01-09-2015 At 09:09 am.
LC-REMON 14.00
OR Liber 558 Page 931 - 931

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2												
3												
4	7							10	11		12	
5												
6	13		17		18		16		14		19	
7												
8	18		20		21		22		23		24	
9												
10	30		28		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, Daniel T. Kibbe, in a field survey on July 9, 20 14, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1855: GLO Alfred Millard, Set post Cor. Of Sect 27, 28, 33 & 34, Maple 10 S36W 44, B Ash 10 N34E 46
1996: Thomas Hall, Porters Survey LCRC Recorded L317Pg947, 1/2" Rod & Cap #33984 at Possible OBT Stump & Stream Crossings, N44°W 6.95' 12" Ash, S84°E 31.31' 7" Maple, S40°E 20.08' 7" Maple, S28°W 17.77' 11" Tw. Maple, S34°W 29.00' Poss. O.B.T. Stump
2013: Carl Kiiskila MDNR Working Drawing Section 34. Position only from Recorded Dimensions (DEP)
References: None Given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

2014: Huron Engineering Found 1/2" Rod & Cap 15410.
& Surveying 2014 References:
Remon S84°E 31.31' 16" Maple (OW)
S32°W 17.58' 14" Tw. Maple (OW)
S41°E 20' +/- 12" Twisted Maple (OW)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2014: Found 1/2" Rod & Cap 15410. Replaced cap with Standard Cap.
References:
S84°E 31.31' 16" Maple (OW) set tag #37278
S32°W 17.58' 14" Tw. Maple (OW) set tag #37378
S11°E 26.73' 14" Maple set tag #37278
N36°E 25.56' 8" Maple set tag # 37278

Ratified by Peer Group
in accordance with P.A. 345
Chairman [Signature]
Date 11-04-2014



Signed by [Signature] Date November 7, 2014

Surveyor's Michigan License No. 37278