

**PRESQUE ISLE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE**
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Located in:

Instrument 201500000077 OR Liber Page 558 933

PRESQUE ISLE
(County)

METZ
(Township)

Corner Code #

1. Public Land Survey

T 33N R 5E

H-11

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

201500000077
Filed for Record in
PRESQUE ISLE COUNTY
CATHY I. IDALSKI, REG OF DEEDS
01-09-2015 At 09:09 am.
LC-REMON 14.00
OR Liber 558 Page 933 - 933

Register of Deeds Stamp & File Number

I, Daniel T. Kibbe, in a field survey on July 9, 2014, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1855: GLO Alfred Millard, Set Qr. Sec. Post, Cedar 4 N70E 5, B. Ash 8 S20W 29
1996: Thomas Hall Porters Survey LCRC Recorded L317Pg947, 1/2" Rod & Cap #33984 by Single Proportion, N13°E 25.98' 10" Ash, N32°E 17.10' 6" Maple, S68°W 7.51' 5" Maple, N83°W 15.94' 6" Maple
1997: Norman Quaine Porters Survey, Survey Records, 1/2" Rod & Cap, References: Same as Above
2002: David Guthrie Alpha Land Survey Records, Exist. 1/2" Rod, References: Same as above, 1/2" Iron Rod by Porters Survey
2013: Carl Kiiskila MDNR Working Drawing Section 34, FD. 1/2" bar with PS cap # 15410, No Witnesses Given

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

2014: Huron Engineering & Surveying 2014 Remon Found 1/2" rod & cap 15410.

References:

N30°E 17.10' 12" Tw. Maple (OW)
N84°W 15.94' 14 Tw. Maple (OW)
S73°W 7.51' 6" Maple (OW)
N10°E 25.94' 10" dead ash (OW)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

2014: Set standard Cap on 1/2" rod

References:

N30°E 17.10' 12" Tw. Maple (OW) Set tag#37278
N84°W 15.94' 14 Tw. Maple (OW) Set tag#37278
S73°W 7.51' 6" Maple (OW) Set tag#37278
S02°E 29.18' 12" Maple Set tag#37278
N10°E 25.94' 10" dead ash (OW)

Relieved by Peer Group
in accordance with P.A. 945
Chairman [Signature]
Date 11-07-2014



Signed by _____

Date November 7, 2014

Surveyor's Michigan License No. 37278

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1973
REVISED JAN., 1983
REVISED OCT. 1995