

MAY 18 1996

CHEBOYGAN COUNTY REMONUMENTATION CORNER

COMMISSION

For corners in
CHEBOYGANLAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Located In: _____ Corner Code # _____

(County) _____

1. Public Land Survey T. 38N R. 3W M-13
T. 37 R. 2W A-1
T. 37 R. 2W
T. 37 R. 2W
T. 37 R. 2W

2. Property Controlling S. T. R.
in Section S. T. R.

3. Miscellaneous S. T. R.
Property in Sec. S. T. R.

RECEIVED
FOR RECORD

96 OCT 30 PM 12:23

James H. Granger

CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, JAMES H. GRANGER, in a field survey on SEPTEMBER 24, 19 96
do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as
required in the current manual of survey instructions of the United States Department of the Interior,
Bureau of Land Management or by a decree of a Court of Law and for that the corner points
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of
Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,
recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	16	17	18	19	20	21	22	23	24				
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1840 Original Survey Set wood post 8" Spruce N55°E 12 lks
John Mullett 8" Spruce S51°W 6 lks

19772 LCRC Set 3/4" pipe
Orlando Doyle # 7319

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" pipe and three Doyle witnesses overgrown.

James H. Granger



LIBER 010 PAGE 180

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

also corners A-13, T38N, R2W A-1, T37N, R2W M-1 T37N, R3W

Set 5/8" x 30" rebar with Remonumentation Cap

8" Tamarack	N23°W	7.41'	Set nail w/tag
8" Tamarack	N43°E	10.56'	Set nail w/tag
6" Tamarack	S76°E	5.08'	Set nail w/tag
8" Tamarack	S39°W	5.82'	Set nail w/tag



Signed by James H. Granger
Surveyor's Michigan License No. 16041

Date 10-10-96