

SURVEY & REMONUMENTATION

CHEBOYGAN COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAY 15 1997
For corners in
CHEBOYGAN

CORNER (County)

Located in:

Corner Code #

1. Public Land Survey

T 37N R 3W

M-2

T R

T 37 R 2W

T R

S T R

S T R

S T R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

RECEIVED
FOR RECORD

96 OCT 30 PM 12: 25

James H. Granger

CLERK/REGISTER
CHEBOYGAN COUNTY, MICHIGAN
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, JAMES H. GRANGER, in a field survey on SEPTEMBER 24, 19 96, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

1840 Original Survey
John Mullett

Set wood post 12" Cedar S17°W 10 lks
12" Cedar N20°E 9 lks


1994 LCRC
Norman Quaine #33984

1" pipe

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" pipe and four witnesses

Monica Rose




LIBER 010 PAGE 181

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
also A-2 T37N, R2W

Set 5/8" x 30" rebar with Remonumentation Cap

1" Pipe			
10" Cedar	S77°E	15.13'	Fd tag
6" Cedar	S61°W	21.16'	Fd tag
18" Cedar	N76°W	15.61'	Fd tag
5" Cedar	N23°E	10.08'	Fd tag



Signed by James H. Granger
Surveyor's Michigan License No. 16041

Date 10-10-96