

CHEBOYGAN COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970RECEIVED
FOR RECORD

99 DEC -6 PM 2:45

For corners in

CHEBOYGAN
(County)

Located in:

Corner Code #

1. Public Land Survey

T 37NR 2W

B-5

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

Wicki Szyszynski
CLERK/REGISTER
CHEBOYGAN COUNTY MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, JAMES H. GRANGER, in a field survey on JULY 9, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:


1855 GLO Resurvey
Harvey Mellen

Set wood post

7" Hemlock N 5°E 3 lks
16" Hemlock S26°E 4 lksSURVEY &
RE-MONUMENTATION

MAR 03 2000

SECTION



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence found. Established position by single proportionate measurement between A-5 and C-5

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" rebar with Remonumentation Cap

10" Maple	South	3.23'	Nail & tag #16041
6" Maple	S74°E	15.06'	Nail & tag #16041
7" Maple	N2°W	13.51'	Nail & tag #16041
10" Maple	S78°W	12.88'	Nail & tag #16041

Signed by James H. Granger
Surveyor's Michigan License No. 16041Date November 12, 1999