

# CHEBOYGAN COUNTY REMONUMENTATION CORNER

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>CHEBOYGAN</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>37NR</u> 2W	<u>C-5</u>
	T <u>  </u> R <u>  </u>	
	T <u>  </u> R <u>  </u>	
	T <u>  </u> R <u>  </u>	
2. Property Controlling in Section	S <u>  </u> T <u>  </u> R <u>  </u>	
	S <u>  </u> T <u>  </u> R <u>  </u>	
3. Miscellaneous Property in Sec.	S <u>  </u> T <u>  </u> R <u>  </u>	
	S <u>  </u> T <u>  </u> R <u>  </u>	

RECEIVED FOR RECORD 12-18-97  
at 11:23 O'Clock A M

*Joanne Spray*

CLERK/REGISTER  
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No.       , Recorded Plat         
5. Private Claims       

JAMES H. GRANGER, in a field survey on JULY 15, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:


3-5 1855 Original Survey Set wood post 20" W. Pine N77°E 1.77 lks  
Harvey Mellen  
1979 Survey 1/2" pipe  
Orlando Doyle #7319

### SURVEY & REMONUMENTATION

FEB 26 1998

### SECTION

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

3-5 Found 1/2" pipe and 4 witnesses from 1979 survey. Replaced with 5/8" rebar and remonumentation cap.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3-5 5/8" rebar and Remonumentation Cap  
14" Tamarack S23°W 42.57' Fd nail and washer  
16" W. Pine N28°W 40.46' Fd nail and washer  
6" Tamarack N80°E 16.38' Fd nail and washer  
4" Spruce N35°E 7.03' Fd nail and washer

LIBER 011 PAGE 27

Signed by James H. Granger  
License No. 16041

Date Nov. 17, 1997 Surveyor's Michigan



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED 14, 1976

REVISED JAN., 1983  
REVISED OCT., 1996