



# Facility Summary Report

*Building Name: Tree Improvement Center/Storage Building*

DNR TagID#: **81372**

Facility Location: **Tree Improvement Center**

Inventory Status: **Verified**

Inventory Date: **07/14/2016**

Managing Agency: **Forest Resources**

Facility Type: **Storage/Workshop**

Facility Use: **Storage/Warehouse**

Building Status: **Active**

Building Manager: **Sheila Clark (906-341-2518)**

Building Telephone: **810-229-9152**

Building Fax: **810-228-9452**

Building Address: **Unknown**

Construction Date: **03/20/1957**

Square Footage: **1,600**

Historical Cost: **\$2,000**

Leased/Own: **DNR-Owned**



Employees at Location: **Yes - 8**

Vacant Workstations: **None**

Electricity: **No**

Water: **No**

Heat: **No**

Storage Space: **No**

## MISC. COMMENTS

## LOCATION INFORMATION

COUNTY NAME	TIER/RANGE	TOWNSHIP NAME	SECTION	QQ	Q	LOTS PAR ID	LATITUDE	LONGITUDE
Livingston	01N - 05E	HAMBURG	04	NE	NE	164015	42.51179938	-83.85443676