

**SURVEY &
REMONUMENTATION**

MAR 16 2001

2000 Newaygo County Remonumentation Project

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970


For corners in
Newaygo
(County)

Located in: _____ Corner Code # _____

VOL. **3**

64

1. Public Land Survey
T 15 N R 11 W
T ___ N R ___ W
T ___ N R ___ W
T ___ N R ___ W
2. Property Controlling
in Section S _____
S _____
S _____
3. Miscellaneous
Property in Sec. S _____
S _____
S _____



Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Norman L. Ochs, in a field survey on August 10, 20 00, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

South One Quarter Corner, Section 14, Norwich Township, Newaygo County, Michigan

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SEBSEQUENT RESTORATION:

G.L.O. Milton Nye 1856 Resurvey
6" Maple for the corner
12" Maple N73°W 5 links (3.30') #1

From The Newaygo County Surveyor's Records
(Probably 1920 Michigan State Highway Department Plans for Highway M-20)

Witness Book #1 Page 70 Station 78+50.7
¾" Pipe
40" Pine Stump N70½°E 98.5' #2
36" Pine Stump N12°W 97.5' #3

OVER ↵


B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 5" square United States Forest Service concrete monument with a 3" in diameter brass disk. The centerline of an East and West bituminous road is 1.5' North. There are no apparent North and South occupations. The condition of the witnesses are as follows: #1 gone, #2 and #3 found remains, #4 thru #8 good condition, #9 same as #4.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Placed a new 8" diameter cast iron monument box over the concrete monument. Accepted the 5" square United States Forest Service concrete monument as a substantial marker for the quarter corner and as a careful and faithful reestablishment of the position of the original corner.

- 12" Ash S30°E 38.48' Found dock spike in West side #4
- 24" Red Oak N10°E 44.11' Set spike with tag in West side #5
- 12"-12" Twin Maple S59°W 81.40' Set spike with tag in North side
- 14" Red Oak N22°W 55.36' Set spike with tag in East side



Signed by Norman L. Ochs
Norman L. Ochs

Date August 15, 2000

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on 8/30/00
Norman L. Ochs, County Representative.

N.L.O.