



DELIVERED TO NEWAYGO CO.
01/29/2014 2:08:21 PM

2013 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: _____ Corner Code #

VOL. 7

283

1. Public Land Survey

T15N R11W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W

L-9

2. Property Controlling
in Section

S
S
S
S

3. Miscellaneous
Property in Sec.

S
S
S
S



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
01/29/2014 3:30:21 PM

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Norman L. Ochs, in a field survey on September 11, 2013 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

One Quarter Corner common to Sections 24 and 25, T15N R11W, Norwich Township

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - Resurvey
Milton Nye, August 8, 1837
Re established old quarter section post
#1 18" White Pine N13°E 19 links (12.54')
#2 14" Maple S31½°E 13 links (8.58')

Patrick N. Johnson, R.L.S. # 47956
Section 25, Section Break 2009
Set Iron - Prorated to GLO between K-9 and M-9
#3 6" White Pine (with blaze) N70°E 17.71'
#4 16" Black Oak (with blaze) S10°E 22.94'
#5 8" Black Oak (with blaze) N87°W 3.65'
#6 12" Black Oak (with blaze) N18°W 22.40'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a ½" x 18" Rerod with plastic cap #47956 (Patrick N. Johnson) projecting 1"± above grade. No apparent occupation to the North, South, East and West. The condition of the witnesses are as follows: #1 and #2 gone, # 3 thru #6 in good condition. The distance from K-9 to L-9 is 2663.74' and from L-9 to M-9 is 2660.35'.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I removed the Rerod and set a 4" diameter Harrison Cast Iron Monument 20" long marked "County Surveyor" # 22439, To project 2"± above grade as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter Corner.

#3 6" White Pine (with blaze) N70°E 17.71'
#4 16" Black Oak (with blaze) S10°E 22.94'
#5 8" Black Oak (with blaze) N87°W 3.65'
#6 12" Black Oak (with blaze) N18°W 22.40'

Found spike in North side
Found spike in East side
Found spike in North side
Found spike in West side

Signed by Norman L. Ochs Date JAN 27, 2014
Norman L. Ochs

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on August 29, 2013
Norman L. Ochs, County Representative.

