

SURVEY &
REMONUMENTATION



DELIVERED TO NEWAYGO CO.
01/22/2008 3:43:01 PM

FEB 0 8 2008

2007 Newaygo County Remonumentation Project

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

VOL. 6 56

- Public Land Survey
T 15 N R 11 W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
- Property Controlling S
in Section S
- Miscellaneous S
Property in Sec. S

LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED AND RECORDED
01/22/2008 4:03:22 PM



Register of Deeds Stamp & File Number

- Lot No. _____ Recorded Plat _____
- Private Claims _____

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Norman L. Ochs, in a field survey on May 25, 2007 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

Quarter corner common to Sections 25 and 36, Norwich Township.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - Resurvey
Milton Nye, 3rd quarter 1856
Re Established old quarter section post
#1 6" Beech S75½°W 15 links (9.9')
#2 7" Beech S33½°E 19 links (12.54')

Duane Wood, R.L.S. #24625
LCRC # 1080, March 22, 1991
Set RR Spike in the centerline of road on tree lines to the N and S
#3 36" Maple Az 220° (S40°W) 43.3'
#4 Telephone Pole Az 290 (N70°W) 84.2'
#5 Corner Fence Post Az 00 (North) 32.7'
#6 Power Pole Az 45 (N45°E) 73.2'

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a Rail Road spike at grade. The corner is on line with remnants of fence running North and South. The corner is in centerline of East and West bituminous road. The condition of the witnesses are as follows: #1 and #2 gone, #3 thru #5 good, #6 gone.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I removed the Rail Road spike and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor #22439" and grouted at surface as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original quarter corner.

#3 42" Maple S38°W 42.72'
#4 Telephone Pole stub N72°W 84.29'
#5 6" diameter corner post North 32.72'
6" Black Oak S10°E 33.13'
Power Pole N07°E 43.94'

Set 40d spike with tag in NW side
Found spike in North side
Found spike in East side
Set 40d spike with tag in West side
Set 40d spike with tag in West side

Signed by Norman L. Ochs
Norman L. Ochs

Date January 16, 2008

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on June 21, 2007
Norman L. Ochs, County Representative.

M.L.O.

