

**SURVEY &  
REMONUMENTATION**

DELIVERED TO NEWAYGO CO  
02/05/2009 3:11:56 PM



MAR 0 2 2009

2008 Newaygo County Remonumentation Project

**SECTION**

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Newaygo  
(County)

Located in: \_\_\_\_\_ Corner Code # \_\_\_\_\_

1. Public Land Survey

T15N R11W  
T15N R10W  
T N R W  
T N R W  
T N R W  
T N R W  
T N R W  
T N R W

M-4 ✓  
A-4

VOL. 6 179

2. Property Controlling  
in Section S \_\_\_\_\_  
3. Miscellaneous S \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_



LINDA M. LANDHEER  
NEWAYGO COUNTY REGISTER OF DEEDS  
RECEIVED AND RECORDED  
02/05/2009 3:19:08 PM

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						

I, Norman L. Ochs, in a field survey on October 27, 2008 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.**

East One Quarter Corner, Section 12, T15N R11W, Norwich Township, Newaygo County and West One Quarter Corner, Section 7, T15N R10W, Big Rapids Township, Mecosta County, Michigan.

**A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:**

GLO - Resurvey  
John Hodgson, 3<sup>rd</sup> quarter 1838  
Set quarter section post  
#1 8" Beech S57°W 37 links (24.42')  
#2 8" Beech N16°W 27 links (17.82')

Duane F. Wood, P.S. # 24625  
Liber 2, Page 170 of Mecosta County Records March 12, 1987  
Set 4" x 36" Concrete Monument at intersection of East and West  
Fence and centerline of road.  
#3 12" Oak S05°E 69.2'  
#4 12" Oak N85°E 34.6'  
#5 24" Oak N80°W 65.7'  
#6 Triple Maple N45°W 59.2' OVER 1/4

**B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:**

I found a Mecosta County Remonumentation at ±0.3' above grade. The corner is online with an East and West fence. The corner is online with a two track road to the North. The centerline of a Southwest two track road is 18' West. The condition of the witnesses are as follows: #1 and #2 gone, #3 did not check, #4 and #5 in good condition, #6 did not check, #7 and #8 in good condition.

**C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:**

I accepted the Mecosta County Remonumentation Monument as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original Quarter corner.

#5 20" - 20" Twin White Oak N80°W 65.44'  
#7 6" Red Oak N37°E 35.81'  
#4 4" - 14" Twin Black Oak N83°E 34.67'  
#8 4" Black Oak S19°W 16.67'

Found spike with tag # 33139 in South side  
Found spike with tag (Mecosta County Remon) in Northeast side  
Found spike with tag (Mecosta County Remon) in South side  
Found spike with tag # 33139 in Southwest side

Signed by Norman L. Ochs  
Norman L. Ochs

Date February 3, 2009

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971  
Revised May 14, 1975  
Revised Jan, 1983

Approved by Peer Review Group on November 5, 2008  
Norman L. Ochs, County Representative

