



SURVEY & REMONUMENTATION

MAR 13 2000

NEWAYGO COUNTY REGISTER OF DEEDS
LINDA M. BROWN

1999 Newaygo County Remonumentation Project
LAND CORNER RECORDATION CERTIFICATE FEB 28 PM 1 17.
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

SECTION

For corners in
Newaygo
(County)

Located in:

Corner Code #

Linda M. Brown

1. Public Land Survey

T 15N R 11W
T R
T R
T R
S T R
S T R
S T R
S T R

M-7

VOL. 2 360

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Norman L. Ochs, in a field survey on November 5, 19 99 do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Northeast Corner, Section 24, Norwich Township, Newaygo County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1838 Resurvey
10" Beech S65°W 26 Links (17.16') #1
10" Beech N09°W 37 Links (24.42') #2

Lyman W. June (Mecosta County Surveyor)
April 26, 1897 Field Book 2, Page 34
No Stake found - Set Post on due West course 74.68 Chains (4928.88') from Southeast corner of Section 18, T15N R10W.

Lyman W. June (Mecosta County Surveyor)
April 22, 24 thru 26, 1899 Field Book 3, Page 54
Stake - one Beech Stump found in place scared.

Delos G. Anderson (County Surveyor)
1900
12" Maple North 20' #3

Lyman W. June (Mecosta County Surveyor)
July 1, 1901 Field Book 4, Page 120
Stake at original corner.

Newaygo County Road Commission Sheet
8" White Oak N12°W 26' #4
8" White Oak S32°E 41' #5

OVER ↵

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1" x 26" Rebar on line ± with red painted trees running East and West. The centerline of old M-20 is 379.6 feet ± North. The condition of the recorded witnesses are: #1 thru #3 gone, #4 thru #7 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rebar and set a 4" diameter Harrison cast iron monument 30" long marked "County Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

20" White Oak N15°W 26.00' Found spike in East side of tree. #4
18" White Oak S38°E 41.90' Found spike in East side of tree. #5
Old M-20 North 379.6' ± #6
16" - 16" Twin White Oak N66°E 29.35' Found spike in North side of tree. #7
10" Red Oak S25°W 7.7' Found spike in North side of tree.

Signed by Norman L. Ochs
Norman L. Ochs

Date November 10, 1999

Surveyor's Michigan License No. 22439

Approved by Peer Review Group on December 16, 1999
Norman L. Ochs, County Representative.

M. R. O.

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Revised May 14, 1975
Revised Jan., 1983

