

**SURVEY &  
REMONUMENTATION**

MAR 02 2009

**SECTION**



DELIVERED TO NEWAYGO CO  
02/05/2009 3:11:56 PM

2008 Newaygo County Remonumentation Project

**LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Newaygo  
(County)

Located in: \_\_\_\_\_ Corner Code # \_\_\_\_\_

1. Public Land Survey

T13N	R11W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W
T N	R W

**VOL. 6**

**138**

2. Property Controlling in Section \_\_\_\_\_ S \_\_\_\_\_

3. Miscellaneous Property in Sec. \_\_\_\_\_ S \_\_\_\_\_



LINDA M. LANDHEER  
NEWAYGO COUNTY REGISTER OF DEEDS  
RECEIVED AND RECORDED  
02/05/2009 3:19:08 PM

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Norman L. Ochs, in a field survey on January 5, 2008 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

**Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.**

Quarter corner common to Sections 15 and 16, T13N R11W, Big Prairie Township.

**A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:**

GLO - James H. Mullett  
4<sup>th</sup> quarter 1837 Set quarter Section Post  
#1 8" Black Oak N39°E 31 links (20.46')  
#2 6" White Oak N73°W 29 links (19.14')

Lyle S. Shepherd, R.L.S. # 503  
Book 21, Page 126  
July 15, 1926  
Fargo Engineering

Copy of field notes on large sheet for entire Township  
Set pipe - Replaced old pine root stake and stone  
#3 12" Black Oak N24¾°W .58 chains (38.28')  
#4 22" Pine Stump N03°E .47½ chains (31.35')  
#5 24" Pine Stump N22½°E .52 chains (34.32') OBT  
#6 10" White Oak N70°E .53 chains (34.98')

OVER ↻

**B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:**


I found a Consumer Power Company Standard Marker with cap. The corner is at point of intersection of a gated two-track road going South and West. The corner is 79.0' West of top of bank of Bayou. The condition of the witnesses are as follows: #1 thru #2 gone, #3 found 12" Stump N24°W 38.50' to center, #4 found remnants of Pine Stump N03°E 31' 50' to center, #5 gone, #6 found 10" Stump N70°E 35.0' to center, #7 thru #9 in good condition.

**C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:**

I accepted the Consumer Power Company Standard Marker with cap 1.8'± below grade as a substantial marker for the corner and is accepted as a careful and faithful reestablishment of the position of the original quarter corner.

#7 20" Black Oak N18°E 2.61'  
#8 20" Black Oak N52°W 20.88'  
#9 20" Black Oak S11°W 16.32'  
10" White Oak S70°W 18.09'

Set spike with tag #22439 in East side  
Found double headed nail in North side  
Set 40d spike with tag #22439 in East side  
Found double headed nail in North side



Signed by Norman L. Ochs  
Norman L. Ochs

Date January 23, 2009

Surveyor's Michigan License No 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971  
Revised May 14, 1975  
Revised Jan , 1983

Approved by Peer Review Group on July 16, 2008  
Norman L. Ochs, County Representative.

*N.L.O.*