

**SURVEY &  
REMONUMENTATION**

AUG 06 2008

**SECTION**

**OSCODA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE**  
Filing Requirement of Act 74, Mich. P.A. 1970



For corners in  
OSCODA  
(County)

Located in: Corner Code #

JERI WINTON  
OSCODA COUNTY

REGISTER OF DEEDS

07/29/2008 09:32:54AM

FEE: \$17.00

PAGES: 2 RCPT#: 8285

LC8-138 CORNER RECORDATION

- 1. Public Land Survey T26N R1E B-7
- 2. Property Controlling S T
- in Section S T
- 3. Miscellaneous S T
- Property in Sec. S T

**APPROVED**

County Remonumentation  
Peer Review Group

*18 JULY 08*

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1	6	5	4	3	2								
2	7	8	9	10	11	12							
3	13	14	15	16	17	18							
4	19	20	21	22	23	24							
5	25	26	27	28	29	30							
6	31	32	33	34	35	36							
7													
8													
9													
10													
11													
12													
13													

- 4. Lot No.      Recorded Plat
- 5. Private Claims

I, Marvin E. Myers, P.S., in a field survey on June 20, 2008 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, re-monumented, re-monumented, recovered, found as expressed below.

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

**B-7 Quarter Section Corner common to Sections 18 & 19 T.26N.-R.1E.**

1839 GLO William R. Coon Deputy Surveyor  
Mon.- Set quarter Section post  
Wit: Y. Pine 6" S79°E 4 ½ lks (2.97')  
Aspen 4" N76°W 15 lks (9.90')

1937 USGLO Dependent Resurvey James T. Boyd and T. Nolan  
Canada, Transitman, Guy Veal, Cadastral Engineer

Mon.- Proportionate distance; there is no remaining evidence of the original post or bearing trees.  
Set an iron post, 3 ft. long, 2 ins. diam., 26 ins. in the ground, for ¼ sec. cor., with brass cap mkd.  
Wit: A Jack Pine, 6 ins. diam., bears N47 ½°E, 21 ½ lks. (14.19') dist., mkd. ¼ S 18 B T.  
A Jack Pine, 9 ins. diam., bears S25 ½°W, 21 lks. (13.86') dist., mkd ¼ S 19 B T.

Part A continued on back: →

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

**B-7 Quarter Section Corner common to Sections 18 & 19 T.26N.-R.1E.**


Found USGLO Pipe with brass cap 8" above ground in pine plantation; found witness post lying on side with USFS location tag; found 9" R Pine with location tag S83°W with blaze 9.37; found S23°E 5.83 13" R Pine with blaze; N36°E 16.12 blazed 12" R Pine Accepted USGLO Pipe with brass cap as a careful and faithful reestablishment of the position of the original corner.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

**B-7 Quarter Section Corner common to Sections 18 & 19 T.26N.-R.1E.**

Mon - USGLO 1" Pipe with brass cap left in place

Wit:  
North 2± Set Carsonite Post  
S83°W 9.37 Set nail and tag in North side in blazed 9" R Pine with location tag  
S23°E 5.83 Set nail and tag in Northeast side of blazed 13" R Pine with location tag  
N36°E 16.12 Set nail and tag in West side of blazed 12" R Pine with location tag  
N30°W 14.77 Set nail and tag in Southwest side 10" R Pine  
N40°E 60± Southwest corner of small cutting in R Pine plantation  
East 100± Centerline of N-S trail to opening in plantation  
South 200± Centerline of E-W Gravel road



Signed by Marvin E. Myers

Surveyor's Michigan License No. 31600

Date

July 14, 2008